

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

	PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAI	NCE BHD		Ref:	CS3/LPC21011548/Vvf3e2	
	300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date:	22/11/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLK 4844E	Veh. Inspected	t	SMD 8219J	
	Policy No.	Z21VP05028250	Coverage (\$)		0.00	
	Claim No.	21/21/21/VP05/025140	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		12/11/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA ESTIMA 2.4G A SR	c.c		2362	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	ACR500073731	Colour		SILVER	
	Odometer	133407 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55Z R17	APLUS		5 mm	
	L/H Front Tyre	215/55Z R17	APLUS		5 mm	
	R/H Rear Tyre	215/55Z R17	APLUS		5 mm	
	L/H Rear Tyre	215/55Z R17	APLUS		5 mm	
4.	Description of Damages					
	THE VEHICLE SUS	EHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	10/11/2021	Inspect Date /	Time	12/11/2021 (10:30 AM)	
	Survey held at	8, Kaki Bukit Avenue 4 @ Premier, #04-20				
	Repairer	A-TEC AUTOMOTIVE PTE LTD				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21011548/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser