

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002553/KGA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210029137
<b>Claimant Vehicle No :</b>	SGT168L	<b>Insured Vehicle No :</b>	SJN1198P
Date of Loss:	14/03/2022	Nature of Claim:	TP
		Claim No:	5449271941SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGT168L</b>	Engine No:	4GR0665715
Make & Model:	LEXUS IS250, 2.5 STD FL (A)	Chassis No:	JTHBK262405123616
Reg. Date:	16/06/2010 (Man. Year: 2010)	Odometer:	132475 km
Colour:	Metallic Pearl White		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Goodyear 3 mm	Rear Left Side:	Goodyear 4 mm
Front Right Side:	Goodyear 3 mm	Rear Right Side:	Goodyear 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,768.86	1,768.23	0.63	0.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	800.00	100.00	11.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,668.86</b>	<b>2,568.23</b>	<b>100.63</b>	<b>3.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,050.00</b>		
<b>(S\$)</b>	2,668.86	2,050.00	618.86	23.19
<b>+ GST 7.00/7.00% (S\$)</b>	186.82	143.50	43.32	23.19
<b>Nett Amount (S\$)</b>	<b>2,855.68</b>	<b>2,193.50</b>	<b>662.18</b>	<b>23.19</b>
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,795.50</b>		

INSPECTION

Date of Assignment:	17/03/2022	
Date Inspected:	17/03/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S FENDER	Buckled	1,063.70 FL	*1,063.00 FL
2	1		*FRONT BUMPER FASCIA	Buckled	752.80 FL	*752.80 FL
3	1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	148.90 FL	*148.90 FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	1,965.40 1,964.70
					- List Item Discount on L Items 10.00/10.00% (\$)	196.54 196.47
					Total Parts (\$)	1,768.86 1,768.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	500.00	440.00
2	TO REMOVE ,CUT-OUT ,DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	400.00	360.00
<b>Gross Labour Cost (\$\$)</b>			<b>900.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >