

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002554/KPA3Q2**Date:** 27/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700059141
Claimant Vehicle No :	SHD5247G	Insured Vehicle No :	SLG3272H
Date of Loss:	16/03/2022	Nature of Claim:	TP
		Claim No:	4091558975SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5247G		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B73698
Reg. Date:	15/11/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU603076688
Colour:	Metallic Pearl White/Red	Odometer:	534745 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,392.47	1,373.62	6,018.85	81.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,990.00	760.00	5,230.00	87.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,382.47	2,133.62	11,248.85	84.06
Approved Total (Overridden) (\$\$)		1,700.00		
(\$\$)	13,382.47	1,700.00	11,682.47	87.30
+ GST 7.00/7.00% (\$\$)	936.77	119.00	817.77	87.30
Nett Amount (\$\$)	14,319.24	1,819.00	12,500.24	87.30
+ Loss of Use (2.5 x S\$50.00/day) (\$\$)		125.00		
+ Car Rental (2.5 x S\$112.35/day) (\$\$)		280.88		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,232.33		
Global Sum Settlement (\$\$)		2,230.00		

INSPECTION

Date of Assignment: 17/03/2022

Date Inspected: 17/03/2022

Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster:KENNETH KONG

Manager:CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2	1		*COVER, REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
3	1		*GUARD ,REAR BUMPER CENTER	Buckled / Dented	576.30 FL	*576.30 FL
4	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
5	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Mtg Broken	123.70 FL	*123.70 FL
6	1		*COVER ,BACK DOOR TRIM	Serviceable	24.90 FL	*- FL
7	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
8	1		*LENS AND BODY, REAR LAMP ,RH	Serviceable	502.00 FL	*- FL
9	1		*LENS & BODY ,REAR COMBINATION LAMP, RH	Cracked	451.80 FL	*451.80 FL
10	1		*COVER SUB-ASSY ,QUARTER PILLAR ,RH	Serviceable	207.30 FL	*- FL
11	1		*PANEL SUB-ASSY ,QUARTER RH	Repair	871.50 FL	*- FL
12	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
13	1		*GARNISH SUB-ASSY BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
14	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
15	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
16	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME ,NO.2	Necessary	54.60 FL	*54.60 FL
17	1		*PLATE BACK DOOR NAME,NO.1	Necessary	54.60 FL	*54.60 FL
18	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
19	1		*PANEL SUB-ASSY ,REAR DOOR, RH	Repair	1,294.90 FL	*- FL
20	1		*HANDLE ASSY ,REAR DOOR OUTSIDE ,RH	Repair	97.40 FL	*- FL
21	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
22	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*60.00 FS
23	1		*REAR TAIL LAMP CLIP	Not Necessary	65.00 FS	*- FS
24	1		*END PANEL INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
25	1		*CLIP (FOR REAR DOOR TRIM BOARD)	Not Necessary	65.00 FS	*- FS
26	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
28	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,378.30	1,811.50
- List Item Discount on L Items 25.00/25.00% (\$)	1,985.83	437.88
Total Parts (\$)	7,392.47	1,373.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	440.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	300.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,990.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >