

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL



We undt 30-9-2028 LAR 21778
Booth 8200

30/5/22 L/S \$ 21,900 informed Elin

AUTOWERKS

ZOOM AUTOWERKS PTE LTD

LKK Auto Consultants henceforth

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

21 March 2022

Acknowledged by Repairer

Signature:

Date:

REG NO.: SMW 41 G
MAKE/MODEL: MASERATI

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear boot lid <i>Warped / one</i>	8,750.00 ✓
2	Rear boot dampers <i>11</i>	400.00 X
2	Rear boot hinges <i>11</i>	1,050.00 X
2	Rear boot lamps <i>n/s n1 o/s one</i>	1,660.00 1PC
1	Rear boot lock <i>11</i>	265.00 X
1	Rear boot rubber <i>SC</i>	441.00 X
1	Rear boot "MASERATI" emblem <i>ALC</i>	27.50
2	Rear taillamps <i>n/s n1 o/s one</i>	4,620.00 1PC
1	Rear end panel - upper <i>DD</i>	2,750.00
1	Rear end panel - lower <i>Body</i>	1,932.00
1	Rear end panel inner garnish <i>Tw1</i>	840.00
1	Rear bumper <i>Dis</i>	8,990.00
2	Rear bumper brackets <i>RF</i>	360.00 X
1	Rear bumper clip (1 set) <i>111</i>	120.00
1	Rear bumper <i>under cover o/s Dis</i>	4,650.00 ✓
1	Rear bumper <i>screw (10 pcs) rivet ALU</i>	60.00
2	Rear bumper retainers <i>o/s one</i>	320.00 1PC
1	Rear bumper tow hook cover <i>Torn</i>	98.00
4	Rear bumper reverse sensor brackets <i>111</i>	640.00 X
4	Rear bumper reverse sensors <i>one o/s</i>	1,280.00 2PC
1	Rear exhaust silencer <i>Dis</i>	6,590.00
2	Rear exhaust mountings <i>Torn</i>	278.00
1	Rear exhaust heat shield <i>Dis</i>	1,239.00
		47,360.50
	Less 10%	4,736.05
		42,624.45

<u>SPECIAL NETT ITEMS</u>		
1	Rear reverse camera <i>11</i>	550.00 X
		550.00

<u>LABOUR CHARGES</u>		
1	To remove, replaced damaged lamps and check up rear wiring.	120.00 20
2	To remove and refit inner garnishes.	180.00 100
3	To remove and refit rear reverse sensor and camera.	180.00 50
4	To transfer boot lid mechanism and wiring assembly.	120.00 80
5	To remove, refit and replace exhaust silencer and mountings.	200.00 100
6	To apply undercoating.	200.00 50
7	Panel beating.	2,000.00 1200
8	To re-spray painting on the affected areas.	1,800.00 1200
		4,800.00

GRAND TOTAL :

p. 27421-62

10%

24679.45

2800

\$ 47,974.45

27479.45

272

21583

21/3/22
21,900 / 7 days?