

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002566/UPA3Q2**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210078928
<b>Claimant Vehicle No :</b>	SML5468J	<b>Insured Vehicle No :</b>	GBH6497U
Date of Loss:	19/03/2022	Nature of Claim:	TP
		Claim No:	4088469153SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SML5468J</b>	Engine No:	HR16942670C
Make & Model:	NISSAN SYLPHY, 1.6 CVT (A)	Chassis No:	MNTBBAB17Z0035738
Reg. Date:	27/05/2019 (Man. Year: 2019)	Odometer:	44460 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Ecopia 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Ecopia 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,191.88	7,000.33	5,191.55	42.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	3,280.00	960.00	22.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,431.88</b>	<b>10,280.33</b>	<b>6,151.55</b>	<b>37.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>16,431.88</b>	<b>8,200.00</b>	<b>8,231.88</b>	<b>50.10</b>
<b>+ Car Rental (11.0 x S\$100.00/day) (S\$)</b>		1,100.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>9,302.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,300.00</b>		

**INSPECTION**

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022	Inspected At: Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	10.0 days	

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	130.80 FN	*89.50 FN
2	1		*REAR BOOT LID	Badly Dented	891.10 FN	*716.80 FN
3	1		*REAR BOOT CHROME MOULDING	Cracked	323.10 FN	*231.00 FN
4	1		*REAR BOOT HINGES	N/S Bent / O/S Repair	191.80 FN	*95.90 FN
5	1		*REAR BOOT INNER TRIM	Warped	143.40 FN	*143.40 FN
6	2		*REAR BOOT LAMPS	Cracked	372.00 FN	*322.80 FN
7	1		*REAR BOOT LOCK	Bent	91.80 FN	*91.80 FN
8	1		*REAR BOOT LOCK CATCH	Not Necessary	47.50 FN	*- FN
9	1		*REAR BOOT LOGO	Necessary	43.80 FN	*43.80 FN
10	1		*REAR BOOT RUBBER	Twisted	74.20 FN	*74.20 FN
11	1		*REAR BOOT SYLPHY EMBLEM	Necessary	62.40 FN	*62.40 FN
12	2		*REAR TAILLAMPS	Cracked	832.00 FN	*832.00 FN
13	2		*REAR TAILLAMP PANELS	Dented / Bent	983.60 FN	*410.00 FN
14	1		*REAR END PANEL	Badly Dented	452.80 FN	*452.80 FN
15	1		*REAR END PANEL INNER GARNISH	Distorted	161.30 FN	*105.10 FN
16	1		*REAR KEYLESS SENSOR	Not Necessary	185.50 FN	*- FN
17	1		*REAR BUMPER	Distorted	784.40 FN	*669.00 FN
18	1		*REAR BUMPER BRACKETS	N/S Dented	183.40 FN	*91.70 FN
19	1		*REAR BUMPER INNER SPONGE	Torn	84.60 FN	*84.60 FN
20	1		*REAR BUMPER REFLECTORS	N/S Cracked	173.20 FN	*45.00 FN
21	2		*REAR BUMPER REFLECTOR COVERS	No such part	156.00 FN	*- FN
22	2		*REAR BUMPER SIDE RETAINERS	Bent / Twisted	85.20 FN	*70.00 FN
23	2		*REAR NUMBER PLATE LAMPS	Not Necessary	116.00 FN	*- FN
24	1		*REAR FLOOR TOP BOARD	Warped	566.00 FN	*488.60 FN
25	1		*REAR FLOOR PANEL	Repair	771.50 FN	*- FN
26	1		*REAR EXHAUST SILENCER	Not Necessary	486.40 FN	*- FN
27	2		*REAR EXHAUST MOUNTINGS	Not Necessary	37.20 FN	*- FN
28	1		*REAR FENDERS	N/S Warped/Buckled /O/S Repair	3,030.60 FN	*1,515.30 FN
29	2		*REAR FENDER AIR GATES	Not Necessary	104.60 FN	*- FN
30	2		*REAR FENDER INNER SHIELDS	Not Necessary	69.00 FN	*- FN
31	2		*REAR FENDER INNER TRIMS	Deformed / Torn	778.00 FN	*778.00 FN
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
34	1		*REAR WEEKEND SEAL	Necessary	45.00 FS	*18.00 FS
35	1		*REAR WEEKEND PLATE	Necessary	50.00 FS	*40.00 FS
36	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
37	1		*REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,433.20</b>	<b>7,741.70</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	1,241.32	741.37
<b>Total Parts (\$\$)</b>	<b>12,191.88</b>	<b>7,000.33</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE ,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
8	TO APPLY UNDERCOATING	New	200.00	100.00
9	PANEL BEATING	New	1,600.00	1,580.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,200.00
<b>Gross Labour Cost (S\$)</b>			<b>4,240.00</b>	<b>3,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >