



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 4452M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LEFT CABIN TOP PANEL	DAMAGED	650.00	650.00
1	LEFT HEADLIGHT	BROKEN	450.00	450.00
1	LEFT DOOR	DAMAGED	180.00	180.00
1	LEFT DOOR HANDLE	BROKEN	80.00	80.00
	LESS 10% DISCOUNT		-	-136.00
			1,360.00	1,224.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE/CUT, WELD KNOCK OUT DENTS TO STRAIGHTEN AREAS AFFECTED BY IMPACTED AS MENTIONED ON THE "PARTS REPAIR" COLUMN INCLUSIVE OF REPLACEMENT PARTS.		1,500.00	800.00
	PUTTY & SPRAY PAINTING TO ADJUSTED PANELS. JOB ALLOWANCE. PANEL / MATERIALS.		800.00	700.00
	APPLY RUST PROOFING ON ADJUSTED PANELS.		80.00	40.00
	REMOVE AND REBUILD LABOUR.	NOT NECESSARY	500.00	-
			2,880.00	1,540.00
GRAND TOTAL			4,240.00	2,764.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,200.00

Report Ref No. CS/GAI22002568/Vty3e2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.