

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002569/ETY3N2**Date:** 06/05/2022**REFERENCE**

Insured/Claimant:	IP SWEE HEE	Policy No:	1800095443	
Date of Loss:	17/03/2022	Nature of Claim:	OD	Claim No: 9044554533SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2213P		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11YP9347
Reg. Date:	08/08/2018 (Man. Year: 2018)	Chassis No:	GF7W0402070
Colour:	Red	Odometer:	91428 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$95,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,028.00	13,206.13	9,821.87	42.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,080.00	5,855.00	4,225.00	41.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,108.00	19,061.13	14,046.87	42.43
- Excess (\$\$)	800.00	800.00	0.00	0.00
(\$\$)	32,308.00	18,261.13	14,046.87	43.48
+ GST 7.00/7.00% (\$\$)	2,261.56	1,278.28	983.28	43.48
Nett Amount (\$\$)	34,569.56	19,539.41	15,030.15	43.48

INSPECTION

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE,FR BUMPER	Broken	851.00 F	*851.00 FL
2	1		*MOULDING,FR BUMPER,LH	Cut	116.00 F	*116.00 FL
3	1		*MOULDING,FR WHEEL ARCH,LH	Cut	160.00 F	*160.00 FL
4	1		*MOULDING,RR WHEEL ARCH,LH	Cut	160.00 F	*160.00 FL
5	1		*MOULDING,RR BUMPER LH	Cut	106.00 F	*106.00 FL
6	1		*INSULATOR,FR FENDER,LH	Not Necessary	60.00 F	*- FL
7	1		*FENDER,FR LH	Dented	622.00 F	*622.00 FL
8	1		*SHIELD,FR WHEELHOUSE,LH	Crushed	164.00 F	*164.00 FL
9	1		*SHIELD,RR WHEEL,RR LH	Not Necessary	22.00 F	*- FL
10	1		*PANEL ASSY,FR DOOR,LH	Dented	930.00 F	*930.00 FL
11	1		*MLDG,F/DR WDO BELT LINE LH	Not Necessary	88.00 F	*- FL
12	1		*HINGE,FR DOOR,LWR RH	Not Necessary	43.00 F	*- FL
13	1		*HINGE,FR DOOR,LWR LH	Bent	43.00 F	*43.00 FL
14	1		*RUNCHANNEL F/DR WDO GLA,LH	Not Necessary	149.00 F	*- FL
15	1		*W/STRIP,F/DR OPENG,LWR LH	Not Necessary	47.00 F	*- FL
16	1		*W/STRIP,FR DR OPNG,INR LH	Not Necessary	204.00 F	*- FL
17	1		*REGULATOR,FR DOOR,WDO LH	Not Necessary	178.00 F	*- FL
18	1		*MOTOR,F/DR POWER WDO REG,L	Not Necessary	457.00 F	*- FL
19	1		*GASKET,F/DR OUTSIDE HANDLE	Not Necessary	6.00 F	*- FL
20	1		*BASE,F/DR OUTSIDE HDLE,LH	Not Necessary	135.00 F	*- FL
21	1		*LATCH,FR DOOR,LH	Not Necessary	322.00 F	*- FL
22	1		*ROD,F/DR OUTSIDE HANDLE,LH	Not Necessary	12.00 F	*- FL
23	1		*CABLE,FR DOOR INS LOCK,LH	Not Necessary	19.00 F	*- FL
24	1		*CHECK,FR DOOR	Not Necessary	31.00 F	*- FL
25	1		*MLDG,R/DR WDO BELT LINE,LH	Not Necessary	79.00 F	*- FL
26	1		*W/STRIP,R/DR OPNG OTR L	Not Necessary	161.00 F	*- FL
27	1		*W/STRIP,R/DR OPN,LWR OTR L	Not Necessary	33.00 F	*- FL
28	1		*W/STRIP,RR DOOR OPNG,FR LH	Torn	129.00 F	*129.00 FL
29	1		*RUNCHAN,R/DR WDO GLASS,LH	Not Necessary	113.00 F	*- FL
30	1		*PANEL ASSY,RR DOOR,LH	Dented	851.00 F	*851.00 FL
31	1		*GLASS,RR DOOR WINDOW,LH	Not Necessary	263.00 F	*- FL
32	1		*W/STRIP,R/DR OPNG,INR LH	Not Necessary	96.00 F	*- FL
33	1		*HINGE,FR DOOR,LWR LH	Not Necessary	43.00 F	*- FL
34	1		*HINGE,RR DOOR,UPR LH	Not Necessary	43.00 F	*- FL
35	1		*REGULATOR,R/DR WINDOW,LH	Not Necessary	177.00 F	*- FL
36	1		*GASKET,R/DR OUTSIDE HANDLE	Not Necessary	6.00 F	*- FL
37	1		*BASE,R/DR OUTSIDE HOLE,LH	Not Necessary	48.00 F	*- FL
38	1		*CHECK,RR DOOR	Not Necessary	32.00 F	*- FL
39	1		*CABLE,RR DOOR INS LOCK,LH	Not Necessary	19.00 F	*- FL
40	1		*CABLE,RR DOOR INS HANDLE,L	Not Necessary	24.00 F	*- FL
41	1		*ROD,R/DR OUTSIDE HANDLE,LH	Not Necessary	11.00 F	*- FL
42	1		*LATCH,RR DOOR,LH	Not Necessary	321.00 F	*- FL
43	1		*TAPE,FR DOOR SASH,LH	Necessary	42.00 F	*42.00 FL
44	1		*TAPE,RR DOOR SASH	Necessary	42.00 F	*42.00 FL
45	1		*TAPE,RR DOOR SASH	Necessary	42.00 F	*42.00 FL
46	1		*GARNISH,FR DOOR,LH	Cut	190.00 F	*190.00 FL
47	1		*GARNISH,RR DOOR,LH	Cut	164.00 F	*164.00 FL
48	1		*AIR DAM,SIDE,LH	Cut	544.00 F	*544.00 FL
49	1		*MIRROR ASSY,DOOR,LH	Cut	558.00 F	*558.00 FL
50	1		*COVER,DOOR MIRROR,OTR LH	Not Necessary	139.00 F	*- FL
51	1		*WHEEL,SPARE TIRE DISC	Cut	1,102.00 F	*1,102.00 FL
52	1		*WHEEL,SPARE TIRE DISC	Cut	1,102.00 F	*1,102.00 FL
53	1		*ARM ASSY,FR SUSP,LWR LH	Not Necessary	325.00 F	*- FL
54	1		*BOLT,FR SUSP LWR ARM	Not Necessary	11.00 F	*- FL
55	1		*BOLT,FR AXLE CROSSMEMBER	Not Necessary	26.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BOLT,FR AXLE CROSSMEMBER	Not Necessary	10.00 F	*- FL
57	1		*BAR,FR SUSP STABILIZER	Not Necessary	317.00 F	*- FL
58	1		*STRUT,FR SUSP,LH	Bent	469.00 F	*469.00 FL
59	1		*INSULATOR,FR SUSP STRUT	Necessary	96.00 F	*96.00 FL
60	1		*BEARING,FR SUSP STRUT	Necessary	32.00 F	*32.00 FL
61	1		*ARM ASSY,RR SUSP,UPR	Not Necessary	109.00 F	*- FL
62	1		*LINK,RR SUSP ASSIST	Not Necessary	86.00 F	*- FL
63	1		*ARM ASSY,RR SUSP TRAIL,LH	Not Necessary	501.00 F	*- FL
64	1		*ARM ASSY,RR SUSP,LWR	Bent	151.00 F	*151.00 FL
65	1		*SHOCK ABSORBER,RR SUSP	Not Necessary	257.00 F	*- FL
66	1		*BAR,RR SUSP STABILIZER	Not Necessary	262.00 F	*- FL
67	1		*SHOCK ABSORBER,RR SUSP	Not Necessary	257.00 F	*- FL
68	1		*ARM ASSY,RR SUSP,LWR	Not Necessary	151.00 F	*- FL
69	1		*ARM ASSY,RR SUSP TRAIL,LH	Bent	501.00 F	*501.00 FL
70	1		*LINK,RR SUSP ASSIST	Bent	86.00 F	*86.00 FL
71	1		*ARM ASSY,RR SUSP,UPR	Bent	109.00 F	*109.00 FL
72	1		*INSUL,RR SHOCK ABSORBER	Not Necessary	57.00 F	*- FL
73	1		*PAD,RR SUSP SPRING,LWR	Not Necessary	19.00 F	*- FL
74	1		*HUB ASSY,RR WHEEL	Bent	434.00 F	*434.00 FL
75	1		*GEAR & LINK ASSY,STEERING	Bent	1,326.00 F	*1,326.00 FL
76	1		*BEARING,FR WHEEL HUB	Necessary	152.00 F	*152.00 FL
77	1		*KNUCKLE,LH	bent	358.00 F	*358.00 FL
78	1		*PANEL,QTR,OTR LH	Dented	1,298.00 F	*1,298.00 FL
79	1		*BODY SEALANT	Necessary	240.00 FS	*120.00 FS
80	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
81	1		*HUB ASSY,FR WHEEL	Necessary	288.00 F	*288.00 FL
82	1		*END ASSY,TIE ROD Supplementary	Bent	63.00 F	*63.00 FL
83	1		*SNAP RING, FR WHEEL HUB Supplementary	Necessary	25.00 F	*25.00 FL
84	1		*LINK, FR SUSP STABILIZER Supplementary	Bent	86.00 F	*86.00 FL
85	1		*BOLT, RR SUSP ASSIST LINK Supplementary	Necessary	8.00 F	*8.00 FL
86	1		*HEADLAMP ASSY, LH Supplementary	Broken	2,439.00 F	*2,439.00 FL
87	1		*CROSSMEMBER, RR SUSP Supplementary	Dented	1,122.00 F	*1,122.00 FL
88	1		*PLATE, RR SUSP ASSIST LINK Supplementary	Necessary	8.00 F	*8.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	23,028.00	17,109.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	3,902.87
Total Parts (\$)	23,028.00	13,206.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RESPRAY ACCIDENT DAMAGED PORTION ON FRONT BUMPER,LH FRONT FENDER,BOTH LH DOORS,LH REAR FENDER,LH ROCKER PANEL,LH B PILLAR,LH WING MIRROR	New	3,150.00	2,475.00
2	RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER,BOTH LH FENDERS,BOTH LH DOORS,REPAIR B PILLAR LH ROCKER PANEL	New	2,700.00	1,750.00
3	TRANSFER LH FRONT DOOR TRIM.MECHANISM,ELECTRONICS TO NEW DOOR	New	450.00	120.00
4	TRANSFER LH REAR DOOR TRIM.MECHANISM,ELECTRONICS TO NEW DOOR	New	450.00	120.00
5	REMOVE REAR SEATS,FLOOR TRIM TO FACILITATE REPAIRS	New	450.00	120.00
6	REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS	New	450.00	0.00
7	RENEW FRONT UNDERCARRIAGE	New	450.00	450.00
8	RENEW REAR UNDERCARRIAGE	New	450.00	450.00
9	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
11	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
12	TRANSFER LHF TYRE TO NEW SPORTS RIM	New	30.00	30.00
13	TRANSFER LH REAR TYRE TO NEW SPORTS RIM	New	30.00	30.00
14	SUPPLY LHF TYRE	New	400.00	0.00
15	SUPPLY LHR TYRE	New	400.00	0.00
16	SUPPLY RIKE COOL SOLAR FILM FOR LHF DOOR	New	120.00	0.00
17	SUPPLY RIKE COOL SOLAR FILM FOR LHR DOOR	New	120.00	0.00
18	SUPPLY ANTI CORROSION	New	160.00	40.00
Gross Labour Cost (\$\$)			10,080.00	5,855.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >