

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002570/KQY3Q2**Date:** 13/09/2022**REFERENCE**

Insured/Claimant: GARY LAU NAM FOONG Policy No: DMPCSNW00147312102

Date of Loss: 08/03/2022

Nature of Claim: OD

Claim No: SNM22D201691/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGR4845A**

Make & Model: MITSUOKA GALUE, 250LX (A)

Engine No: VQ25309526A

Reg. Date: 09/02/2007 (Man. Year: 2006)

Chassis No: Y50152782

Colour: Metallic Silver

Odometer: 200897 km

Engine Capacity: 2495 cc

Market Value/New Car Price: S\$95,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,469.50	19,479.50	17,990.00	48.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	2,020.00	2,530.00	55.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,019.50	21,499.50	20,520.00	48.83
Approved Total (Overridden) (S\$)		17,200.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	40,519.50	15,700.00	24,819.50	61.25

INSPECTION

Date of Assignment: 20/03/2022

Date Inspected: 21/03/2022 Inspected At:

Sin Heng Long Motor Work (Ang Mo Kio)
Blk 5032 Ang Mo Kio Industrial Park 2, #01-305
Singapore 569535

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2022)
Parts:	143	MITSUOKA GALUE 250LX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR4845A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	3,000.00 F	*3,000.00 F
2	1		*FRONT BONNET (WCP)	Cracked	6,500.00 F	*6,500.00 F
3	1		*FRONT GRILLE (WCP)	Missing	4,200.00 F	*4,200.00 F
4	1		*RH FRONT HEAD LAMP (WCP)	Serviceable	3,500.00 F	*- F
5	1		*LH FRONT HEAD LAMP (WCP)	Serviceable	3,500.00 F	*- F
6	1		*RH FOG LIGHT (WCP)	Serviceable	450.00 F	*- F
7	1		*LH FOG LIGHT (WCP)	Serviceable	450.00 F	*- F
8	1		*BONNET LOCK (WCP)	Distorted	380.00 F	*380.00 F
9	1		*SET FRONT BUMPER SMALL LAMP KIT (WCP)	Broken	1,400.00 F	*1,400.00 F
10	1		*FRONT BUMPER CHROME LH (WCP)	Dented	450.00 F	*450.00 F
11	1		*FRONT BUMPER CHROME RH (WCP)	Dented	450.00 F	*450.00 F
12	1		*FRONT BUMPER CHROME CENTER (WCP)	Dented	700.00 F	*700.00 F
13	1		*RH FOG LIGHT COVER (WCP)	Missing	150.00 F	*150.00 F
14	1		*LH FOG LIGHT COVER (WCP)	Missing	150.00 F	*150.00 F
15	1		*FRONT GRILLE EMBLEM (WCP)	Missing	215.00 F	*215.00 F
16	1		*RH FRONT FENDER (WCP)	Repair	2,000.00 F	*- F
17	1		*LH FRONT FENDER (WCP)	Repair	2,000.00 F	*- F
18	1		*RADIATOR (WCP)	Serviceable	2,850.00 F	*- F
19	1		*REINFORCEMENT BEAM (WCP)	Repair	1,400.00 F	*- F
20	1		*CAR PLATE & FRAME	Bent	50.00 FS	*45.00 FS
21	1		*CLIPS & NUT & SCREWS (60 PCS)	Necessary	300.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	34,095.00	17,720.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	3,374.50	1,759.50
Total Parts (\$\$)	37,469.50	19,479.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	2,400.00	900.00
2	SPRAY FENDERS ,DOORS ,BONNET & BUMPER	New	1,800.00	1,100.00
3	WIRING	New	150.00	20.00
4	ANTI RUST	New	120.00	0.00
5	ELECTRONIC & LIGHT TESTING	New	80.00	0.00
Gross Labour Cost (\$)			4,550.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >