Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Jenny Lew Date: 21 Mar 2022

Preliminary Advice

Vehicle No : SGR4845A Accident Date : 08/03/2022

Make : MITSUOKA Policy No.

> **GALUE** DMPCSNW00147312102

Assignment **Excess** : 20/03/2022 : S\$1,500.00

Date

Date of : 21/03/2022 Est. Duration of

: 7 Inspection Repair

Inspection At: SIN HENG LONG MOTOR WORK (ANG MO KIO)

BLK 5032 ANG MO KIO INDUSTRIAL PARK 2, #01-305

SINGAPORE 569535

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 42,019.50 **Revised Amount** :S\$ 19,956.50 Check Items (Estimated) :S\$ 11,993.00 Total :S\$ 31,949.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

:S\$ 95,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 25,434.00 Salvage Value :S\$

Margin for Repair :S\$ 69,566.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.