

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22002572/AGQY3E2

**Date:** 18/05/2022

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001490065  
Claimant Vehicle No : SLH3546M Insured Vehicle No : FBG7785L  
Date of Loss: 14/03/2022 Nature of Claim: TP Claim No: 271311

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH3546M**  
Make & Model: VOLKSWAGEN TIGUAN, 1.4 TSI BMT (5N22SY) (A) Engine No: CTH237930  
Reg. Date: 31/10/2016 (Man. Year: 2016) Chassis No: WVGZZZ5NZGW070920  
Colour: Grey Odometer: 89236 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/40 R19 Rear Tyre Size: 255/40 R19  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,562.14	4,133.27	3,428.87	45.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,400.00	1,830.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,792.14</b>	<b>5,533.27</b>	<b>5,258.87</b>	<b>48.73</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,792.14</b>	<b>4,400.00</b>	<b>6,392.14</b>	<b>59.23</b>

### INSPECTION

Date of Assignment: 21/03/2022  
Date Inspected: 21/03/2022 Inspected At: 10 KAKI BUKIT ROAD 2#03-01 FIRST EAST CENTRE S(417868)  
Estimated Period of Repair: 5.0 days Repairer: Polymath Garage Pte Ltd - Kaki Bukit (HQ)

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2022)

**Parts:** M1-SUV VOLKSWAGEN TIGUAN 1.4 TSI BMT (5N22SY) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLH3546M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,145.60 FL	*1,145.60 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	76.20 FL	*- FL
3	1		*REAR BUMPER REFLECTOR (RED) LH	Cracked	65.20 FL	*65.20 FL
4	1		*REAR BUMPER REFLECTOR (WHITE) LH	Cracked	68.10 FL	*68.10 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	554.90 FL	*- FL
6	1		*REAR BUMPER LOWER BRACKET	Deformed	459.50 FL	*459.50 FL
7	2		*REVERSE SENSOR	Damaged (1 PCS ONLY)	450.00 FL	*245.00 FL
8	4		*REVERSE SENSOR HOLDER	Necessary	72.00 FL	*72.00 FL
9	1		*TAILLAMP LH	Not Necessary	485.20 FL	*- FL
10	1		*TAILGATE	Dented	1,674.60 FL	*1,674.60 FL
11	1		*TAILGATE LOCK	Not Necessary	248.10 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Not Necessary	221.40 FL	*- FL
13	1		*TAILGATE REFLECTOR LH	Cracked	385.20 FL	*385.20 FL
14	1		*VOLKSWAGEN LOGO	Necessary	130.90 FL	*130.90 FL
15	1		*TIGUAN EMBLEM	Necessary	104.20 FL	*104.20 FL
16	1		*TSI EMBLEM	Necessary	62.20 FL	*62.20 FL
17	1		*BLUEMOTION EMBLEM	Necessary	57.80 FL	*57.80 FL
18	1		*REAR END PANEL	Repair	648.90 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	261.10 FL	*- FL
20	1		*REAR EXHAUST PIPE	Not Necessary	869.40 FL	*- FL
21	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	35.90 FL	*- FL
22	1		*REAR EXHAUST PIPE GASKET	Not Necessary	48.20 FL	*- FL
23	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
24	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
26	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
28	1		*SET REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,374.60</b>	<b>4,580.30</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	812.46	447.03
<b>Total Parts (S\$)</b>	<b>7,562.14</b>	<b>4,133.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	40.00
5	TO REMOVE UPHOLSTERY	New	150.00	30.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	120.00
8	TO REMOVE EXHAUST PIPE	New	150.00	0.00
			<b>Gross Labour Cost (\$)</b>	<b>1,400.00</b>
			<b>3,230.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >