6/2/22, 2:03 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22002573/RVY3N2

Singapore 079909 Date: 02/06/2022

REFERENCE

Insured/Claimant: TAN WEE KIAT Policy No: DMPCSNW00216502100

Date of Loss: 14/03/2022 Nature of Claim: OD Claim No: SNM22D201830/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNB6640L

Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A) Engine No: CZC138866

Reg. Date: 23/02/2017 (Man. Year: 2016) Chassis No: WVWZZZAUZHW047828

Colour: Blue Odometer: 70766 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$64,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,850.00	3,600.00	250.00	6.49
Miscellaneous Items	80.00	60.00	20.00	25.00
Labour	714.00	730.80	-16.80	-2.35
Paintwork Labour	252.00	517.44	-265.44	-105.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,896.00	4,908.24	-12.24	-0.25
Approved Total (Overridden) (S\$)		3,900.00		
- Excess (S\$)	500.00	0.00	500.00	100.00
(S\$)	4,396.00	3,900.00	496.00	11.28
+ GST 7.00/7.00% (S\$)	307.72	273.00	34.72	11.28
Nett Amount (S\$)	4,703.72	4,173.00	530.72	11.28

INSPECTION

Date of Assignment: 21/03/2022 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

Auto Insure Pte Ltd (HQ) (Woodlands)

Date Inspected: 21/03/2022 Inspected At: 6 Marsiling Lane

Singapore 739145

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/2/22, 2:03 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2022)

Parts: 144 VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB6640L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*PARTS		3,850.00 F	*3,600.00 F
r-rialiolise part.		Total Parts (S\$)	3,850.00	3,600.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRAS		80.00	60.00
	Sub Total (S\$)	80.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	LABOUR FOR SPRAY PAINTING	New	252.00	517.44
<u>Lab</u>	<u>our Items</u>			
2	LABOUR FOR PANEL BEATING	New	714.00	730.80
		Gross Labour Cost (S\$)	966.00	1,248.24
	Report v	was unsubmitted during this print-out.		