



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 7877Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	COVER, RR BUMPER, L (SN)	TO REPAIR SEE LABOUR	335.20	-
1	EXTENSION, RR BUMPER (SN)	GRAZED	201.40	201.40
1	PANEL SUB-ASSY, BACK (SN)	TO REPAIR SEE LABOUR	1,199.60	-
1	FRONT BONNET EMBLEM (SN)	SERVICEABLE	72.20	-
1	PLATE, BACK DOOR NAM (SN)	SERVICEABLE	37.60	-
1	PLATE, BACK DOOR NAM (SN)	SERVICEABLE	56.40	-
			1,932.40	231.40
	<b><u>LABOUR</u></b>			
	TO RESET ECU AND REPROGRAMME.	NOT NECESSARY	180.00	-
	REPLACE REAR ACCIDENT DAMAGED PARTS. STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER, L AND PANEL SUB-ASSY, BACK.		1,440.00	720.00
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS.		1,770.00	885.00
			3,390.00	1,605.00
<b>GRAND TOTAL</b>			<b>5,322.40</b>	<b>1,836.40</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,836.40</b>

Report Ref No. CS/UOI22002574/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.