

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002585/ETY3N2**Date:** 28/04/2022**REFERENCE**

Insured/Claimant:	YEM AI LIN	Policy No:	1900104708		
Date of Loss:	20/03/2022	Nature of Claim:	OD	Claim No:	3628640297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML8443K		
Make & Model:	KIA STONIC, 998cc DCT (A)	Engine No:	G3LCJP143388
Reg. Date:	07/06/2019 (Man. Year: 2018)	Chassis No:	KNAD6811VK6244902
Colour:	Brown	Odometer:	35544 km
Engine Capacity:	998 cc		
Market Value/New Car Price:	S\$76,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,138.80	4,692.00	446.80	8.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,640.00	790.00	23.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,568.80	7,332.00	1,236.80	14.43
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	7,968.80	6,732.00	1,236.80	15.52
+ GST 7.00/7.00% (S\$)	557.82	471.24	86.58	15.52
Nett Amount (S\$)	8,526.62	7,203.24	1,323.38	15.52

INSPECTION

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER UPR	Broken	493.00 FL	*493.00 FL
2	1		*SKID PLATE-FR BUMPER	Broken	55.00 FL	*55.00 FL
3	1		*GRILLE ASSY-RADIATOR	Not Necessary	324.00 FL	*- FL
4	1		*COVER-RADIATOR GRILLE UPR	Not Necessary	46.00 FL	*- FL
5	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	98.00 FL	*98.00 FL
6	1		*LIP ASSY-FRONT BUMPER	Not Necessary	32.00 FL	*- FL
7	1		*GRILLE-FRONT BUMPER	Cut	96.00 FL	*96.00 FL
8	1		*MOULDING-FRONT BUMPER A/INTAKE	Cut	61.00 FL	*61.00 FL
9	1		*AIR DUCT-FR BUMPER,LH	Not Necessary	38.00 FL	*- FL
10	1		*COVER-FR BUMPER FOG LAMP LH	Cut	64.00 FL	*64.00 FL
11	1		*BRACKET-FR BUMPER SIDE,LH	Not Necessary	13.00 FL	*- FL
12	1		*COVER-FR BUMPER,LWR	Cut	367.00 FL	*367.00 FL
13	1		*LAMP ASSY-HEAD,LH	Broken	1,845.00 FL	*1,845.00 FL
14	1		*PANEL ASSY-HOOD	Dented	1,135.00 FL	*1,135.00 FL
15	1		*HINGE ASSY-HOOD,LH	Not Necessary	43.00 FL	*- FL
16	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
17	1		*BODY SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*ORNAMENT-KIA NO. 115 Supplementary	Necessary	38.00 FL	*38.00 FL
19	1		*COOLANT (4L) Supplementary	Necessary	26.00 FL	*26.00 FL
20	1		*AIR GUIDE-INTERCOOLER Supplementary	Broken	35.00 FL	*35.00 FL
21	1		*STIFFNER-FR BPR LWR Supplementary	Crushed	170.00 FL	*170.00 FL
22	1		*BEAM COMPLETE-FR BUMPER Supplementary	Dented	751.00 FL	*751.00 FL
23	1		*CARRIER ASSY-FRONT END MODULE Supplementary	Bent	556.00 FL	*556.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,396.00	5,850.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,257.20	1,158.00
Total Parts (\$\$)	5,138.80	4,692.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PORTION ON FRONT BUMPER,BONNET,REPAIR LH FRONT FENDER	New	1,200.00	800.00
2	RESPRAY FRONT BUMPER,BONNET,LH FRONT FENDER	New	1,400.00	1,050.00
3	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
5	AUPPLY ANTI CORROSION	New	80.00	40.00
6	REPLACE FRONT SUPPORT PANEL Supplementary	New	400.00	400.00
7	VACUUM & TOP UP A/COND GAS Supplementary	New	80.00	80.00
8	REMOVE & REINSTALL A/COND CONDENSOR & RADIATOR TO FACILITATE REPAIR Supplementary	New	120.00	120.00
Gross Labour Cost (\$\$)			3,430.00	2,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >