

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002586/ETY3N2**Date:** 05/04/2022**REFERENCE**

Insured/Claimant:	MEHENDALE SURJIT SHYAM	Policy No:	1700022215	
Date of Loss:	19/03/2022	Nature of Claim:	OD	Claim No: 5258520475SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB1284A		
Make & Model:	MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CP5609		
Reg. Date:	30/06/2017 (Man. Year: 2017)	Chassis No:	JMYSRCY1AGU006924
Colour:	Silver	Odometer:	43122 km
Engine Capacity:	1590 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,865.09	2,309.16	555.93	19.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	2,015.00	675.00	25.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,555.09	4,324.16	1,230.93	22.16
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	4,955.09	3,724.16	1,230.93	24.84
+ GST 7.00/7.00% (\$\$)	346.86	260.69	86.17	24.84
Nett Amount (\$\$)	5,301.95	3,984.85	1,317.10	24.84

INSPECTION

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,RH	Broken	851.00 FL	*851.00 FL
2	1		*FACE,FR BUMPER	Broken	1,045.00 FL	*1,045.00 FL
3	1		*GRILLE,FR BUMPER	Broken	78.00 FL	*78.00 FL
4	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	70.00 FL	*- FL
5	1		*BRACKET,FR BUMPER SIDE RH	Not Necessary	17.00 FL	*- FL
6	1		*GRILLE,RADIATOR	Broken	270.00 FL	*270.00 FL
7	1		*REINFORCEMENT,FR BUMPER	Dented	531.00 FL	*531.00 FL
8	1		*FENDER,FR RH	Repair	622.00 FL	*- FL
9	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
10	1		*FRT NUMBER PLATE WITH FRAME	Broken	50.00 FS	*50.00 FS
11	1		*COVER. FR BUMPER Supplementary	Missing	38.00 FL	*38.00 FL
12	1		*COVER. FR BUMPER GRILLE Supplementary	Missing	5.00 FL	*5.00 FL
13	1		*CLIPS (X10) Supplementary	Necessary	40.00 FL	*40.00 FL
14	1		*RIVETS (X10) Supplementary	Necessary	50.00 FL	*50.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					3,697.00	2,978.00
- List Item Discount on L Items 23.00/23.00% (\$)					831.91	668.84
Total Parts (\$)					2,865.09	2,309.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,FRT RH FENDER & AFFECTED AREA	New	1,350.00	675.00
2	PAINT WORK ON FRT BUMPER & FRT RH FENDER	New	700.00	700.00
3	PERFORM RUST PREVENTION	New	40.00	40.00
4	CHECK CHASSIS & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
6	RESPRAY ON HEADLAMP SUPPORT PANEL & FRONT BUMPER RE-INFORCEMENT	New	175.00	175.00
	Supplementary			
7	REPAIR HEADLAMP SUPPORT PANEL & REPLACE FRONT BUMPER RE-INFORCEMENT	New	275.00	275.00
	Supplementary			
Gross Labour Cost (\$\$)			2,690.00	2,015.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >