



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDINGSINGAPORE 079120 ATTN: LOH CHEE HENG			Ref: CS3/AIG21008797/Vqy3n2-1 Date: 07/04/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMR 4116A	Veh. Inspected	GBD 2456K	
Policy No.		Coverage (\$)	0.00	
Claim No.	1095103661SG	Excess (\$)	0.00	
Assign From	LOH CHEE HENG	Assign Date	21/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KDY2318016275	Colour	SILVER	
Odometer	140271 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/75 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	185/75 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	165 R13C	BRIDGESTONE	5 mm	
L/H Rear Tyre	165 R13C	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/08/2021	Inspection Date	02/09/2021	
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	