### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB22002590/UTY3E2

**Date:** 09/05/2022

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

Claimant Vehicle SMK1772L Insured Vehicle No : SLV1947D

No: SIVIN 1772L Insured Verlicie No: SLV 1947D

Date of Loss: 19/03/2022 Nature of Claim: TP Claim No: MFL2022D0001425

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMK1772L

 Make & Model:
 HONDA FIT, 1.3 GF CVT (A)
 Engine No:
 L13B1447800

 Reg. Date:
 29/03/2019 (Man. Year: 2018)
 Chassis No:
 GK31339905

 Colour:
 Blue
 Odometer:
 23396 km

Engine Capacity: 1317 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 7 mm
Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,725.20	4,104.32	3,620.88	46.87
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,850.00	1,900.00	950.00	33.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	10,575.20	6,004.32	4,570.88	43.22
Ар	proved Total (Overridden) (S\$)		4,800.00		
	Nett Amount (S\$)	10,575.20	4,800.00	5,775.20	54.61

**INSPECTION** 

Date of Assignment: 21/03/2022

Leang Automotive (Kaki Bukit)

Date Inspected: 21/03/2022 Inspected At: AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6

#01-68

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2022)

Parts: 143 HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK1772L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

		Particulars	Condition	Repairer's	Amount
1		*FRONT BUMPER	Dented / Deformed	855.10 FL	*681.20 FL
2		*FRONT BUMPER SIDE RETAINERS	Necessary	56.00 FL	*56.00 FL
1		*FRONT BUMPER LOWER CENTRE GRILLE	Twisted	108.20 FL	*108.20 FL
1		*FRONT BUMPER BEAM	Dented	296.40 FL	*296.40 FL
1		*SET FRONT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
1		*FRONT GRILLE CHROME	Cracked	292.30 FL	*292.30 FL
1		*FRONT GRILLE CHROME LOWER	Cracked	171.00 FL	*171.00 FL
1		*FRONT GRILLE	Cracked	226.10 FL	*226.10 FL
1		*FRONT GRILLE H LOGO	Scratched	35.00 FL	*35.00 FL
1		*FRONT RADAR SENSOR	Serviceable	2,145.00 FL	*- FL
2		*HEADLAMPS	Cracked	1,590.40 FL	*1,590.40 FL
2		*HEADLAMP LOWER BRACKETS	Cracked	77.80 FL	*77.80 FL
1		*FRONT SUPPORT PANEL	Repair	474.30 FL	*- FL
1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	118.20 FL	*- FL
1		*BONNET	Dented	606.20 FL	*606.20 FL
1		*BONNET LOCK	Twisted	90.80 FL	*90.80 FL
1		*AIR CON CONDENSER	Punctured	810.00 FL	*810.00 FL
1		*RADIATOR	Serviceable	1,248.20 FL	*- FL
1		*FRONT FENDER O/S	Repair	366.50 FL	*- FL
1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FL	*50.00 FL
nchise	part. L=ListIte	emDisc.	-		
			Sub Total (S\$)	9,656.50	5,130.40
- List Item Discount on L Items 20.00/20.00% (S\$)				1,931.30	1,026.08
			Total Parts (S\$)	7,725.20	4,104.32
	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 1 1 1 1 1 1 1 1 2 2 2 1 1 1 1 1 1 1	*FRONT BUMPER SIDE RETAINERS  *FRONT BUMPER LOWER CENTRE GRILLE  *FRONT BUMPER BEAM  *SET FRONT BUMPER CLIPS  *FRONT GRILLE CHROME  *FRONT GRILLE CHROME LOWER  *FRONT GRILLE  *FRONT GRILLE  *FRONT GRILLE  *FRONT GRILLE H LOGO  *FRONT RADAR SENSOR  *HEADLAMPS  *HEADLAMPS  *HEADLAMP LOWER BRACKETS  *FRONT SUPPORT PANEL  *FRONT SUPPORT PANEL TOP GARNISH  *BONNET  *BONNET  *BONNET  *BONNET LOCK  *AIR CON CONDENSER  *RADIATOR  *FRONT FENDER O/S  *FRONT LICENCE PLATE W/HOLDER	***FRONT BUMPER SIDE RETAINERS**  ***FRONT BUMPER LOWER CENTRE GRILLE**  **FRONT BUMPER BEAM**  Dented**  ***FRONT BUMPER CLIPS**  Necessary**  **FRONT GRILLE CHROME**  Cracked**  **FRONT GRILLE CHROME LOWER**  FRONT GRILLE CHROME LOWER**  FRONT GRILLE H LOGO**  FRONT GRILLE H LOGO**  FRONT RADAR SENSOR**  Cracked**  **FRONT RADAR SENSOR**  Cracked**  **HEADLAMPS**  Cracked**  **HEADLAMP LOWER BRACKETS**  FRONT SUPPORT PANEL**  FRONT SUPPORT PANEL**  FRONT SUPPORT PANEL TOP GARNISH**  FRONT SUPPORT PANEL TOP GARNISH**  Serviceable**  **BONNET**  BONNET**  BONNET**  BONNET LOCK**  **BONNET LOCK**  **AIR CON CONDENSER**  **AIR CON CONDENSER**  **RADIATOR**  Serviceable**  **FRONT FENDER O/S**  **FRONT LICENCE PLATE W/HOLDER**  Cracked**  **Cracked**  Cracked**  **Cracked**  **	2 *FRONT BUMPER SIDE RETAINERS Necessary 56.00 FL 1 *FRONT BUMPER LOWER CENTRE GRILLE Twisted 108.20 FL 1 *FRONT BUMPER BEAM Dented 296.40 FL 1 *SET FRONT BUMPER CLIPS Necessary 39.00 FL 1 *FRONT GRILLE CHROME Cracked 292.30 FL 1 *FRONT GRILLE CHROME Cracked 171.00 FL 1 *FRONT GRILLE CHROME LOWER Cracked 171.00 FL 1 *FRONT GRILLE H LOGO Scratched 35.00 FL 1 *FRONT RADAR SENSOR Serviceable 2,145.00 FL 2 *HEADLAMPS Cracked 77.80 FL 2 *HEADLAMPS Cracked 77.80 FL 1 *FRONT SUPPORT PANEL Repair 474.30 FL 1 *FRONT SUPPORT PANEL Repair 474.30 FL 1 *BONNET Dented 606.20 FL 1 *BONNET DENTED BENDER GRANISH SERVICEABLE 118.20 FL 1 *FRONT FENDER O/S Repair 366.50 FL 1 *FRONT FENDER O/S Repair 366.50 FL 1 *FRONT LICENCE PLATE W/HOLDER Cracked 50.00 FL 1 *FRONT LICENCE PLATE W/HOLDER Cracked 50.00 FL 1 *FRONT LICENCE PLATE W/HOLDER CRACKED SUB TOTAL (\$\$) 9,656.50  - List Item Discount on L Items 20.00/20.00% (\$\$) 1,931.30

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO REFILL AIR CON GAS	New	120.00	100.00
4	TO RESET & DIAGNOSTIC SYSTEM	New	100.00	50.00
5	TO APPLY KLAR COATING PROTECTION	New	500.00	300.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	520.00
7	TO PUTTY & SPRAY PAINTING	New	1,200.00	880.00
		Gross Labour Cost (S\$)	2,850.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >