

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002591/KEA3Q2**Date:** 20/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070167559
<b>Claimant Vehicle No :</b>	SFR3111C	<b>Insured Vehicle No :</b>	SMW8511P
Date of Loss:	14/03/2022	Nature of Claim:	TP
		Claim No:	4358911366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFR3111C</b>	Engine No:	1ZZ3222925
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	JTDER12W003001649
Reg. Date:	16/01/2009 (Man. Year: 2008)	Odometer:	230401 km
Colour:	Metallic Pearl White		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,233.82	790.87	442.95	35.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	610.00	90.00	12.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,933.82</b>	<b>1,400.87</b>	<b>532.95</b>	<b>27.56</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,100.00</b>		
<b>(S\$)</b>	1,933.82	1,100.00	833.82	43.12
<b>+ GST 7.00/7.00% (S\$)</b>	135.37	77.00	58.37	43.12
<b>Nett Amount (S\$)</b>	<b>2,069.19</b>	<b>1,177.00</b>	<b>892.19</b>	<b>43.12</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>(S\$)</b>		1,417.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>708.50</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>710.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>710.00</b>		

INSPECTION

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR N/S TAILLAMP	Cracked	472.60 FL	*472.60 FL
2	1		*REAR END PANEL -OUTER	Repair	590.60 FL	*- FL
3	1		*REAR BUMPER FASCIA	Buckled	470.70 FL	*470.70 FL
4	1		*REAR N/S BUMPER SIDE RETAINER	Distorted	57.10 FL	*57.10 FL
5	1		*REAR N/S BUMPER REFLECTOR	Cracked	54.10 FL	*54.10 FL
					<b>Sub Total (\$)</b>	<b>1,645.10</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>411.28</b>
					<b>Total Parts (\$)</b>	<b>1,233.82</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	400.00	360.00
2	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	300.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>700.00</b>	<b>610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >