

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22002603/VPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100462763
<b>Claimant Vehicle No :</b>	SNC1135G	<b>Insured Vehicle No :</b>	SLC352B
Date of Loss:	20/03/2022	Nature of Claim:	TP
		Claim No:	4086591993SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SNC1135G</b>	Engine No:	DEM034040
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF5XMA059848
Reg. Date:	28/09/2021 (Man. Year: 2021)	Odometer:	10207 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	6 mm	Rear Left Side:	6 mm
Front Right Side:	6 mm	Rear Right Side:	6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	35,940.00	1,564.80	34,375.20	95.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,672.00	2,272.00	9,400.00	80.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>47,612.00</b>	<b>3,836.80</b>	<b>43,775.20</b>	<b>91.94</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	3,332.84	268.58	3,064.26	91.94
<b>Nett Amount (\$\$)</b>	<b>50,944.84</b>	<b>4,105.38</b>	<b>46,839.46</b>	<b>91.94</b>
<b>+ Car Rental (4.0 x S\$150.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>4,707.38</b>		

INSPECTION

Date of Assignment:	24/03/2022		
Date Inspected:	24/03/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,493.00 FS	*- FS
2	2		*FRONT BUMPER SECURING STRIP	Repair	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE -CENTER	Serviceable	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Serviceable	293.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Serviceable	599.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	293.00 FS	*- FS
7	2		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	Serviceable	302.00 FS	*- FS
8	2		*FRONT BUMPER TRIM -LH/RH	Serviceable	108.00 FS	*- FS
9	1		*FRONT BUMPER TRIM -CENTER	Serviceable	127.00 FS	*- FS
10	1		*RADIATOR GRILLE	Scratched	1,881.00 FS	*1,504.80 FS
11	1		*RADIATOR GRILLE COVER CAP	Serviceable	141.00 FS	*- FS
12	1		*RADIATOR GRILLE BRACKET	Serviceable	19.00 FS	*- FS
13	1		*RADIATOR GRILLE SECURING PLATE	Serviceable	12.00 FS	*- FS
14	1		*FRONT CAMERA	Serviceable	1,261.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	163.00 FS	*- FS
16	1		*FRONT BUMPER REINFORCEMENT BEAM	Serviceable	899.00 FS	*- FS
17	1		*FRONT BUMPER TOP COVER	Serviceable	143.00 FS	*- FS
18	1		*CAUTION STICKER	Serviceable	16.00 FS	*- FS
19	1		*AIR COND STICKER	Serviceable	9.00 FS	*- FS
20	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Serviceable	82.00 FS	*- FS
21	2		*FRONT BUMPER BRACKET -LH/RH	Serviceable	508.00 FS	*- FS
22	1		*FRONT BUMPER LOCK CARRIER BRACKET	Serviceable	154.00 FS	*- FS
23	2		*FRONT BUMPER SUPPORT -LH/RH	Serviceable	64.00 FS	*- FS
24	4		*POP RIVET	Serviceable	4.00 FS	*- FS
25	2		*FRONT PARKING AIR SENSOR -INNER	Serviceable	530.00 FS	*- FS
26	4		*FRONT PARKING AIR SENSOR SEAL RING	Serviceable	10.00 FS	*- FS
27	1		*SET FRONT BUMPER WIRING	Serviceable	449.00 FS	*- FS
28	2		*HORN -LH/RH	Serviceable	273.00 FS	*- FS
29	2		*HORN SUPPORT -LH/RH	Serviceable	66.00 FS	*- FS
30	1		*BONNET	Serviceable	3,491.00 FS	*- FS
31	1		*BONNET ATTACHMENT PARTS	Serviceable	128.00 FS	*- FS
32	3		*BONNET IMPACT PROTECTION -CENTER -LH/RH	Serviceable	93.00 FS	*- FS
33	2		*BONNET STICKER -LH/RH	Serviceable	112.00 FS	*- FS
34	2		*BONNET LOCK	Serviceable	455.00 FS	*- FS
35	1		*BONNET BOWDEN CABLE -CENTER	Serviceable	64.00 FS	*- FS
36	1		*BONNET RELEASE LEVER	Serviceable	15.00 FS	*- FS
37	1		*BONNET BOWDEN CABLE -OUTER	Serviceable	64.00 FS	*- FS
38	1		*BONNET RELEASE CABLE COVER	Serviceable	11.00 FS	*- FS
39	2		*HEADLIGHT MATRIX BEAM -LH/RH	Serviceable	16,344.00 FS	*- FS
40	2		*LIFT CYLINDER -LH/RH	Serviceable	434.00 FS	*- FS
41	2		*LIFT CYLINDER BRACKET -LH/RH	Serviceable	34.00 FS	*- FS
42	1		*LIFT CYLINDER CORRUGATED PIPE	Serviceable	107.00 FS	*- FS
43	1		*LOCK CARRIER	Serviceable	1,127.00 FS	*- FS
44	2		*LOCK CARRIER SUPPORT -LH/RH	Serviceable	85.00 FS	*- FS
45	6		*RADIATOR COOLANT	Serviceable	282.00 FS	*- FS
46	1		*A/C CONDENSER	Serviceable	683.00 FS	*- FS
47	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Serviceable	21.00 FS	*- FS
48	1		*CHARGE AIR COOLER	Serviceable	654.00 FS	*- FS
49	2		*RADIATOR AIR GUIDE -LH/RH	Serviceable	72.00 FS	*- FS
50	2		*RADIATOR AIR GUIDE INNER -LH/RH	Serviceable	38.00 FS	*- FS
51	1		*RADIATOR AIR GUIDE UPPER	Serviceable	19.00 FS	*- FS
52	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
53	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **35,940.00**    **1,564.80**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	0.00
3	TO REMOVE AND RENEW AIRCON CONDENSER ,CHARGE AIR COOLER AND RADIATOR CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,700.00	0.00
4	TO CARRY OUT PRESSURISE VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER ,BONNET AND BOTH HEADLIGHT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	4,800.00	500.00
6	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>11,672.00</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >