

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002612/ATCE2

Date: 01/06/2022

REFERENCE

Insured/Claimant:	TAY HUP HUAT	Policy No:	1900090699-01	
Date of Loss:	19/03/2022	Nature of Claim:	OD	Claim No: 6392343763SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC1453M		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK077141
Reg. Date:	23/04/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF49KA042009
Colour:	Black	Odometer:	59734 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$132,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,138.00	5,208.96	23,929.04	82.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,352.00	4,062.00	8,290.00	67.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,490.00	9,270.96	32,219.04	77.65
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	40,890.00	8,670.96	32,219.04	78.79
+ GST 7.00/7.00% (S\$)	2,862.30	606.97	2,255.33	78.79
Nett Amount (S\$)	43,752.30	9,277.93	34,474.37	78.79

INSPECTION

Date of Assignment:	22/03/2022		
Date Inspected:	21/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	2,377.00 FS	*- FS
2	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	40.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
5	1		*FRONT FENDER - RH	Repair	861.00 FS	*- FS
6	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	81.00 FS	*- FS
7	1		*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
8	1		*FRONT FENDER BRACE - RH	Not Necessary	132.00 FS	*- FS
9	6		*FRONT FENDER POP RIVET	Not Necessary	23.00 FS	*- FS
10	1		*FRONT FENDER BRACKET CENTER - RH	Not Necessary	55.00 FS	*- FS
11	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	262.00 FS	*- FS
12	1		*FRONT WHEEL SPOILER	Not Necessary	82.00 FS	*- FS
13	1		*FRONT FENDER LEDGE COVER LONG - RH	Not Necessary	35.00 FS	*- FS
14	1		*FRONT FENDER LEDGE COVER SHORT - RH	Not Necessary	26.00 FS	*- FS
15	1		*BONNET	Not Necessary	3,425.00 FS	*- FS
16	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Not Necessary	93.00 FS	*- FS
17	1		*HEADLIGHT - RH	Not Necessary	8,294.00 FS	*- FS
18	1		*FRONT DOOR - RH	Dented	3,431.00 FS	*2,744.80 FS
19	1		*FRONT DOOR OUTER SEAL - RH	Necessary	229.00 FS	*182.80 FS
20	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
21	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
22	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
23	1		*FRONT DOOR BUNGS	Not Necessary	5.00 FS	*- FS
24	1		*FRONT DOOR CATCH - RH	Not Necessary	116.00 FS	*- FS
25	1		*WING MIRROR MOUNTING - RH	Damaged	991.00 FS	*792.80 FS
26	1		*WING MIRROR CAP - RH	Repair	308.00 FS	*- FS
27	1		*WING MIRROR GLASS - RH	Shattered	1,757.00 FS	*1,405.60 FS
28	1		*TYRE PRESSURE DATA PLATE	Necessary	42.00 FS	*33.36 FS
29	1		*FRONT DOOR CORNER TRIM - RH	Not Necessary	51.00 FS	*- FS
30	1		*FRONT DOOR WINDOW GUIDE TRIM STRIP - RH	Not Necessary	287.00 FS	*- FS
31	1		*FRONT DOOR WINDOW GUIDE - RH	Not Necessary	501.00 FS	*- FS
32	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	344.00 FS	*- FS
33	1		*FRONT DOOR HANDLE TRIM PLATE - RH	Not Necessary	98.00 FS	*- FS
34	1		*FRONT DOOR HANDLE CAP COVER - RH	Not Necessary	7.00 FS	*- FS
35	1		*FRONT STONE CHIP GUARD - RH	Cut	57.00 FS	*45.28 FS
36	1		*REAR DOOR - RH	Repair	3,431.00 FS	*- FS
37	1		*REAR DOOR OUTER SEAL - RH	Not Necessary	229.00 FS	*- FS
38	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
39	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
40	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
41	1		*REAR DOOR BUNGS	Not Necessary	5.00 FS	*- FS
42	1		*REAR DOOR SEALING STRIP	Not Necessary	19.00 FS	*- FS
43	1		*REAR DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
44	1		*REAR DOOR WINDOW SLOT SEAL TRIM STRIP - RH	Not Necessary	410.00 FS	*- FS
45	1		*RHS FRONT RIM	Repair	0.00 FS	*- FS
46	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
47	1		*SUNDRIES	Necessary	300.00 FS	*4.32 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **29,138.00** **5,208.96**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
2	TO REMOVE AND TRANSFER RHS FRONT DOOR RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	700.00	280.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS REAR DOOR. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS	New	4,500.00	1,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR, DOOR HANDLE AND RHS SILL PANEL	New	5,500.00	2,350.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	240.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE, CHECK AND TRANSFER, FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
8	TO REAPPLY PAINT COATING ON AFFECTED AREA (Supplementary)	New	350.00	0.00
Gross Labour Cost (\$\$)			12,352.00	4,062.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >