

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002613/KEA3Q2**Date:** 08/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210075107
<b>Claimant Vehicle No :</b>	SMX6531P	<b>Insured Vehicle No :</b>	SJG6036C
Date of Loss:	18/03/2022	Nature of Claim:	TP
		Claim No:	3569110786SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMX6531P</b>	Engine No:	G4FMLU209705
Make & Model:	HYUNDAI CN7 AVANTE, 1.6 DOHC CVT S (A)	Chassis No:	KMHLN41ETMU112034
Reg. Date:	25/01/2021 (Man. Year: 2020)	Odometer:	8641 km
Colour:	Metallic Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Hankook 9 mm	Rear Left Side:	Hankook 9 mm
Front Right Side:	Hankook 9 mm	Rear Right Side:	Hankook 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,858.32	1,144.08	714.24	38.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	340.00	640.00	65.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,838.32</b>	<b>1,484.08</b>	<b>1,354.24</b>	<b>47.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	198.68	103.89	94.79	47.71
<b>Nett Amount (S\$)</b>	<b>3,037.00</b>	<b>1,587.97</b>	<b>1,449.03</b>	<b>47.71</b>
<b>+ Loss of Use (1.0 x S\$60.00/day) (S\$)</b>		60.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,649.97</b>		

INSPECTION

Date of Assignment:	22/03/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	22/03/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	1.0 days	

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cut	1,430.10 FL	*1,430.10 FL
2	1		*FRONT BUMPER	Repair	620.50 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	45.60 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER RH	Serviceable	126.70 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
6	1		*FRONT HEADLAMP CLIPS RH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,302.90</b>	<b>1,430.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	444.58	286.02
<b>Total Parts (S\$)</b>	<b>1,858.32</b>	<b>1,144.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	400.00	100.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREAS &ETC	New	400.00	220.00
3	TO TUFF KOTE & UNDERSEAL MATERIALS	New	100.00	0.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
			<b>Gross Labour Cost (\$)</b>	<b>340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >