

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22002614/EVCE2**Date:** 18/11/2022**REFERENCE****Insured/Claimant:** KHOO RONGWEN (QIU YONGWEN)**Policy No:** 1900108509**Date of Loss:** 17/03/2022**Nature of Claim:** OD **Claim No:** 4312789649SG**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** SML9740X**Make & Model:** AUDI A3, 999cc TFSI S TRONIC (LED) (A)**Engine No:** CHZC27820**Reg. Date:** 13/06/2019 (Man. Year: 2019)**Chassis No:** WAUZZZ8V0K1025220**Colour:** Grey**Odometer:** 44039 km**Engine Capacity:** 999 cc**Market Value/New Car Price:** S\$108,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES**Front Tyre Size:** 225/40R18**Rear Tyre Size:** 225/40R18**Front Left Side:** Goodyear 4 mm**Rear Left Side:** Goodyear 4 mm**Front Right Side:** Goodyear 4 mm**Rear Right Side:** Goodyear 4 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,571.00	2,044.04	10,526.96	83.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,504.00	4,154.00	2,350.00	36.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,075.00	6,198.04	12,876.96	67.51
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,475.00	5,598.04	12,876.96	69.70
+ GST 7.00/7.00% (S\$)	1,293.25	391.86	901.39	69.70
Nett Amount (S\$)	19,768.25	5,989.90	13,778.35	69.70

INSPECTION**Date of Assignment:** 22/03/2022**Date Inspected:** 22/03/2022 **Inspected At:**

24 Benoi Sector Singapore 629857

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 6.0 days**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUSPENSION SUBFRAME	Not Necessary	1,105.00 FS	*- FS
2	1		*BONDED RUBBER BUSHES	Not Necessary	116.00 FS	*- FS
3	1		*TRACK CONTROL ARM	Bent	393.00 FS	*314.00 FS
4	1		*STABILIZER	Not Necessary	451.00 FS	*- FS
5	1		*FRONT WHEEL BEARING HOUSING	Necessary	627.00 FS	*501.20 FS
6	1		*FRONT GUIDE JOINT-LH	Necessary	134.00 FS	*107.20 FS
7	1		*FRONT WHEELHUB BEARING	Necessary	553.00 FS	*442.00 FS
8	1		*COUPLING ROD	Not Necessary	105.00 FS	*- FS
9	1		*DRIVE SHAFT-LH	Not Necessary	1,517.00 FS	*- FS
10	1		*GAS SHOCK ABSORBER	Bent	281.00 FS	*224.80 FS
11	1		*TRACK ROD	Bent	98.00 FS	*78.40 FS
12	1		*TIE ROD END-LH	Bent	126.00 FS	*100.40 FS
13	1		*STEERING GEAR	Not Necessary	5,538.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	183.00 FS	*- FS
15	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	93.00 FS	*- FS
16	1		*NOISE INSULATION	Not Necessary	376.00 FS	*- FS
17	1		*LHS FRONT TYRE	Torn	125.00 FS	*125.00 FS
18	2		*LHS RIM-FRONT & REAR (NPA)	Repair	0.00 FS	*- FS
19	1		*SUNDRIES	Necessary	700.00 FS	*111.12 FS
20	1		*REPAIR SET OF STEERING BOX (Supplementary)	Necessary	50.00 FS	*39.92 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	12,571.00	2,044.04
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT BUMPER WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO DISMANTLE AND REINSTALL FRONT BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVE	New	1,400.00	500.00
3	TO RESPRAY FRONT BUMPER	New	1,400.00	550.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	2,400.00
5	TO RENEW LHS FRONT RIM WITH TYRE AND LHS REAR RIM.TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	320.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			6,504.00	4,154.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >