

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002615/AEA3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800019009
Claimant Vehicle No :	SJX661Y	Insured Vehicle No :	SLW7944S
Date of Loss:	19/03/2022	Nature of Claim:	TP
		Claim No:	8676863833SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX661Y	Engine No:	K9KF649D058595
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Chassis No:	VF1RFA00561665859
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	53514 km
Colour:	Red		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,950.35	9,343.68	16,606.67	63.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	1,770.00	2,660.00	60.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,380.35	11,113.68	19,266.67	63.42
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	30,380.35	8,800.00	21,580.35	71.03
+ GST 7.00/7.00% (S\$)	2,126.62	616.00	1,510.62	71.03
Nett Amount (S\$)	32,506.97	9,416.00	23,090.97	71.03
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,918.00		
Global Sum Settlement (S\$)		9,900.00		

INSPECTION

Date of Assignment:	22/03/2022	
Date Inspected:	22/03/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,452.96 FL	*1,310.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Distorted	685.68 FL	*685.68 FL
3	2		*REAR BUMPER SIDE RETAINER	Cracked	455.52 FL	*455.52 FL
4	2		*REAR BUMPER BRACKET	Cracked	230.20 FL	*230.20 FL
5	1		*REAR BUMPER BEAM	Cracked	235.60 FL	*235.60 FL
6	1		*REAR BUMPER LOWER SPOILER	Deformed	696.24 FL	*696.24 FL
7	1		*REAR BUMPER LOWER SPOILER PROTECTOR	Deformed	492.78 FL	*492.78 FL
8	2		*REAR BUMPER UNDER SIDE COVER	Not Necessary	446.80 FL	*- FL
9	2		*REAR BUMPER REFLECTOR	Not Necessary	571.20 FL	*- FL
10	1		*REAR BUMPER TOW COVER	Not Necessary	78.20 FL	*- FL
11	2		*REAR BUMPER SENSOR BIG	Damaged	447.20 FL	*447.20 FL
12	4		*REAR BUMPER SENSOR SMALL	Not Necessary	760.08 FL	*- FL
13	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	815.80 FL	*- FL
14	1		*REAR END PANEL OUTER	Dented	934.12 FL	*750.00 FL
15	1		*REAR END PANEL TOP GARNISH	Not Necessary	338.30 FL	*- FL
16	2		*REAR END PANEL SIDE BRACKET	Not Necessary	921.20 FL	*- FL
17	1		*REAR END PANEL INNER	Repair	920.40 FL	*- FL
18	1		*REAR WEATHERSTRIPE	Cut	258.40 FL	*258.40 FL
19	1		*REAR SPARE TYRE COMPARTMENT PANEL	Repair	1,482.44 FL	*- FL
20	1		*REAR SPARE TYRE UNDER COVER	Not Necessary	568.70 FL	*- FL
21	1		*REAR SPARE TYRE COMPARTMENT TOP BOARD	Not Necessary	594.70 FL	*- FL
22	1		*REAR TAILGATE	Cracked	2,547.72 FL	*2,045.00 FL
23	1		*REAR TAILGATE OUTER GARNISH	Deformed	748.40 FL	*748.40 FL
24	1		*REAR TAILGATE LOCK	Damaged	328.10 FL	*328.10 FL
25	1		*REAR TAILGATE LOCK LEVEL /DETECTOR	Not Necessary	128.70 FL	*- FL
26	1		*REAR TAILGATE OUTER MOULDING	Cracked	187.40 FL	*187.40 FL
27	1		*REAR TAILGATE REFLECTOR	N/S Cut	880.00 FL	*440.00 FL
28	1		*REAR TAILGATE WINDSCREEN GLASS WITH MOULDING	Necessary	2,445.80 FL	*195.00 FL
29	1		*REAR TAILGATE LOGO	Necessary	124.80 FL	*124.80 FL
30	1		*REAR TAILGATE EMBLEM RENAULT	Necessary	129.60 FL	*129.60 FL
31	1		*REAR TAILGATE EMBLEM SCENIC	Necessary	151.44 FL	*151.44 FL
32	2		*REAR TAILLAMP	Not Necessary	845.70 FL	*- FL
33	2		*REAR TAILLAMP LOWER BRACKET	Not Necessary	275.60 FL	*- FL
34	1		*REAR EXHAUST MUFFLER	Not Necessary	1,845.70 FL	*- FL
35	1		*REAR EXHAUST MUFFLER ALUMINIUM SHIELD	Dented	259.40 FL	*259.40 FL
36	2		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	130.80 FL	*- FL
37	2		*REAR FENDER	Not Necessary	2,682.40 FL	*- FL
38	2		*REAR FENDER INNER SHIELD	Not Necessary	431.20 FL	*- FL
39	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
40	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
41	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
42	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
43	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
44	1		*REAR BUMPER UNDER SIDE COVER CLIPS	Not Necessary	60.00 FS	*- FS
45	1		*REAR REVERSE CAMERA	Not Necessary	420.00 FS	*- FS
46	1		*RIVET CLIPS (30 PCS)	Necessary	234.00 FS	*40.00 FS
47	1		*REAR NUMBER PLATE WITH CASING	Dented	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	28,703.28	10,360.76
- List Item Discount on L Items 10.00/10.00% (\$)	2,752.93	1,017.08
Total Parts (\$)	25,950.35	9,343.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,000.00	700.00
2	LABOUR FOR SPRAY PAINTING	New	1,400.00	700.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING /RUST PROOF ACCIDENT AREAS	New	300.00	60.00
5	LABOUR FOR REMOVE & TRANSFER REAR TAILGATE FITTING	New	200.00	60.00
6	LABOUR FOR REMOVE & RENEW REAR CAMERA AND REVERSE SENSOR	New	300.00	100.00
7	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (\$)			4,430.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >