

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/GRB22002616/UPA3Q2**Date:** 30/03/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : GBF2040R**Insured Vehicle No :** SLV1973C

Date of Loss: 21/03/2022

Nature of Claim: TP

Claim No: MFL2022D0001314

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBF2040R**

Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A)

Engine No: K9KC400D055747

Reg. Date: 04/08/2016 (Man. Year: 2016)

Chassis No: VSKYBAM20Z0127275

Colour: Silver

Odometer: 161522 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size: 185/70 R14

Front Left Side: Comfort 6 mm

Rear Left Side: Comfort 6 mm

Front Right Side: Comfort 6 mm

Rear Right Side: Comfort 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,168.20	3,920.00	8,248.20	67.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	1,740.00	2,520.00	59.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,428.20	5,660.00	10,768.20	65.55
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	16,428.20	4,500.00	11,928.20	72.61
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,827.45		

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 22/03/2022 Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Mar 2023)	
Parts:	N/A	NISSAN NV200 1.5 D MT ABS AIRBAG 2WD 6DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF2040R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR N/S	Repair	1,610.10 F	*- FL
2	1		*REAR BACK DOOR NV 200 EMBLEM N/S	Necessary	205.30 F	*85.50 FL
3	1		*REAR BACK DOOR REAR LOGO N/S	Not Necessary	66.80 F	*- FL
4	1		*REAR BACK DOOR OUTER HANDLE N/S	Not Necessary	168.50 F	*- FL
5	1		*REAR BACK DOOR LOWER LOCK N/S	Not Necessary	299.30 F	*- FL
6	1		*REAR BACK DOOR INNER TRIM N/S	Not Necessary	625.10 F	*- FL
7	1		*SET REAR BACK DOOR INNER TRIM CLIPS N/S	Not Necessary	25.00 F	*- FL
8	1		*REAR BACK DOOR O/S	Badly Dented	1,615.10 F	*1,053.70 FL
9	1		*REAR BACK DOOR DCI EMBLEM O/S	Necessary	66.80 F	*66.80 FL
10	1		*REAR BACK DOOR LOWER LOCK O/S	Damaged	299.30 F	*145.00 FL
11	1		*REAR BACK DOOR INNER RUBBER O/S	Twisted	288.50 F	*91.10 FL
12	1		*REAR BACK DOOR INNER TRIM O/S	Torn	605.10 F	*285.00 FL
13	1		*SET REAR BACK DOOR INNER TRIM CLIPSO/S	Necessary	30.00 F	*30.00 FL
14	1		*REAR BUMPER	Deformed	822.30 F	*485.90 FL
15	1		*REAR BUMPER REFLECTORS	N/S Not Necessary / O/SCracked	120.00 F	*58.00 FL
16	1		*REAR BUMPER SPONGE	Torn	288.00 F	*182.00 FL
17	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	190.00 F	*- FL
18	1		*TAILLAMPS	N/S Not Necessary / O/SCracked	960.00 F	*304.90 FL
19	1		*REAR END PANEL	Dented	655.20 F	*345.00 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	311.30 F	*145.80 FL
21	1		*REAR END PANEL WEATHERSTRIP	Twisted	366.50 F	*221.30 FL
22	1		*REAR FLOOR PANEL	Repair	1,420.00 F	*- FL
23	1		*REAR BACK DOOR GLASS SEALANT N/S	Not Necessary	50.00 FS	*- FS
24	1		*70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
25	1		*REAR BACK DOOR GLASS SEALANT O/S	Necessary	50.00 FS	*40.00 FS
26	1		*6 PAX STICKER	Necessary	20.00 FS	*10.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
28	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET REAR CORPORATE STICKER	Necessary	680.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,168.20	4,270.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	350.00
Total Parts (\$\$)	12,168.20	3,920.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX O/S BACK DOOR GLASS	New	300.00	100.00
4	TO DISMANTLE & REFIX O/S BACK DOOR MECHANISM	New	200.00	60.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO SPRAY RUST PROOFING	New	120.00	60.00
7	TO CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	750.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (\$\$)			4,260.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >