

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22002618/DPA3Q2**Date:** 12/12/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01  
**Claimant Vehicle No :** SHC2608Z **Insured Vehicle No :** SML941S  
 Date of Loss: 18/03/2022 Nature of Claim: TP Claim No: MFL2022D0001414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC2608Z**  
 Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B94683  
 Reg. Date: 05/03/2019 (Man. Year: 2018) Chassis No: JTDKB3FU803078796  
 Colour: Blue Odometer: 402473 km  
 Engine Capacity: 1798 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm  
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,559.90	14,401.95	19,157.95	57.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,840.00	2,680.00	4,160.00	60.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,399.90</b>	<b>17,081.95</b>	<b>23,317.95</b>	<b>57.72</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>15,300.00</b>		
<b>(S\$)</b>	40,399.90	15,300.00	25,099.90	62.13
<b>+ GST 7.00/7.00% (S\$)</b>	2,827.99	1,071.00	1,756.99	62.13
<b>Nett Amount (S\$)</b>	<b>43,227.89</b>	<b>16,371.00</b>	<b>26,856.89</b>	<b>62.13</b>
<b>+ Loss of Use (12.0 x S\$40.00/day) (S\$)</b>		480.00		
<b>+ Car Rental (12.0 x S\$129.68/day) (S\$)</b>		1,556.16		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>+ Other Costs (S\$)</b>		80.00		
<b>Nett Liability (S\$)</b>		<b>18,494.61</b>		

INSPECTION

Date of Assignment: 21/03/2022  
 Date Inspected: 21/03/2022 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)  
 Estimated Period of Repair: 10.0 days Blk 9 Sector C, #01-42 Sin Ming Industrial Estate  
 Singapore 575644

**Adjuster:** BRYAN TANI**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2022)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC2608Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER	Serviceable	112.70 FL	*- FL
3	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
4	1		*REAR BUMPER SIDE CLIP	Not Necessary	25.00 FL	*- FL
5	1		*SEAL ,REAR BUMPER SIDE ,LH	Repair	148.40 FL	*- FL
6	1		*REAR FENDER LH	Dented	836.70 FL	*836.70 FL
7	1		*REAR FENDER SHIELD (LH)	Not Necessary	174.20 FL	*- FL
8	1		*REAR DOOR RUBBER SEAL OUTER	Serviceable	257.90 FL	*- FL
9	1		*PANEL SUB-ASSY ,REAR DOOR ,LH	Buckled	1,258.30 FL	*1,258.30 FL
10	1		*REAR DOOR HINGE UPPER	Bent	82.30 FL	*82.30 FL
11	1		*REAR DOOR HINGE LOWER	Bent	82.30 FL	*82.30 FL
12	1		*REAR DOOR CHECK	Not Necessary	153.00 FL	*- FL
13	1		*REAR DOOR TRIMBOARD	Not Necessary	725.00 FL	*- FL
14	1		*REAR DOOR INNER LOCK	Not Necessary	644.70 FL	*- FL
15	1		*MOTOR ,POWER WINDOW REGULATOR REAR ,LH	Not Necessary	941.80 FL	*- FL
16	1		*REGULATOR DOOR WINDOW REAR ,LH	Not Necessary	228.40 FL	*- FL
17	1		*REAR DOOR OUTER HANDLE	Not Necessary	93.00 FL	*- FL
18	1		*REAR DOOR RUBBER SEAL OUTER	Not Necessary	257.90 FL	*- FL
19	1		*PANEL SUB-ASSY ,FRONT DOOR ,LH	Buckled	1,264.00 FL	*1,264.00 FL
20	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	378.90 FL	*- FL
21	1		*FRONT DOOR INNER LOCK	Damaged	688.80 FL	*688.80 FL
22	1		*FRONT DOOR HINGE UPPER	Bent	91.20 FL	*91.20 FL
23	1		*FRONT DOOR HINGE LOWER	Bent	91.20 FL	*91.20 FL
24	1		*FRONT DOOR CHECK	Not Necessary	153.52 FL	*- FL
25	1		*FRONT DOOR TRIMBOARD	Not Necessary	725.00 FL	*- FL
26	1		*REAR DOOR WEATHERSTRIP	Necessary	457.90 FL	*457.90 FL
27	1		*REAR DOOR RUBBER SEAL	Not Necessary	257.00 FL	*- FL
28	1		*MOTOR ASSY POWER WINDOW FRT ,LH	Not Necessary	941.80 FL	*- FL
29	1		*REGULATOR ,FRONT DOOR WINDOW FRT ,LH	Not Necessary	228.40 FL	*- FL
30	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Not Necessary	1,728.70 FL	*- FL
31	1		*KEY LOCK ANTENNA	Not Necessary	312.00 FL	*- FL
32	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
33	1		*ROCKER PANEL OUTER GARNISH	Bent /Cut	576.00 FL	*576.00 FL
34	1		*ROCKER PANEL OUTER GARNISH CLIP	Necessary	65.00 FL	*65.00 FL
35	1		*REAR TYRE RIM (LH)	Cut	1,555.00 FL	*1,555.00 FL
36	1		*REAR WHEEL CAP (LH)	Not fitted	177.70 FL	*- FL
37	1		*REAR WHEEL BEARING & HUB ASSY	Damaged	610.20 FL	*610.20 FL
38	1		*REAR SHOCK ABSORBER	Distorted	118.30 FL	*118.30 FL
39	1		*REAR SHOCK ABSORBER MOUNTING	Not Necessary	125.30 FL	*- FL
40	1		*REAR LOWER ARM	Distorted	497.50 FL	*497.50 FL
41	1		*REAR UPPER ARM	Distorted	356.80 FL	*356.80 FL
42	1		*REAR KNUCKLE ARM	Distorted	810.60 FL	*810.60 FL
43	1		*REAR STABILIZER BAR	Not Necessary	311.50 FL	*- FL
44	1		*REAR STABILIZER LINK	Not Necessary	151.60 FL	*- FL
45	1		*REAR TRAILING ARM	Distorted	314.20 FL	*314.20 FL
46	1		*REAR ASSIST ARM	Distorted	342.20 FL	*342.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT BUMPER COVER	Bent	499.90 FL	*499.90 FL
48	1		*LAMP ASSY ,FOG ,LH	Not Necessary	920.00 FL	*- FL
49	1		*UNIT ASSY ,HEADLAMP LH (LED)	Mtg Broken	3,455.00 FL	*2,637.60 FL
50	1		*HEAD LAMP PANEL (LH)	Not Necessary	240.10 FL	*- FL
51	1		*TOP PANEL CENTRE	Not Necessary	364.98 FL	*- FL
52	1		*TOP PANEL SIDE	Not Necessary	145.90 FL	*- FL
53	1		*FENDER SUB-ASSY ,FRONT LH	Buckled	945.30 FL	*945.30 FL
54	1		*FRONT HOUSING ASSY	Not Necessary	958.30 FL	*- FL
55	1		*FRONT FENDER SHIELD	Deformed	38.00 FL	*38.00 FL
56	1		*FRONT FENDER SHIELD CLIP	Necessary	14.90 FL	*14.90 FL
57	1		*FRONT FENDER HYBRID EMBLEM ,LH	Necessary	86.50 FL	*86.50 FL
58	1		*BRACKET ,FRONT SIDE PANEL ,LH	Repair	86.30 FL	*- FL
59	1		*EXTENSION ,FRONT FENDER ,LH	Not Necessary	47.20 FL	*- FL
60	1		*PROTECTOR FRONT FENDER UPPER ,LH	Not Necessary	46.10 FL	*- FL
61	1		*GUSSET FRONT FENDER APRON LOWER LH	Not Necessary	34.90 FL	*- FL
62	1		*MEMBER ,FRONT APRON TO COWL SIDE ,UPPER LH	Not Necessary	138.40 FL	*- FL
63	1		*FRONT APRON TO COWL SIDE ,LOWER FRT LH	Not Necessary	82.30 FL	*- FL
64	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	208.60 FL	*- FL
65	1		*FRONT WINDSCREEN GLASS MOULDING LOWER	Not Necessary	208.60 FL	*- FL
66	1		*FRONT WINDSCREEN GLASS PILLAR	Dented	343.10 FL	*343.10 FL
67	1		*FRONT WHEEL RIM	Cut	1,570.55 FL	*1,570.55 FL
68	1		*FRONT WHEEL CAP (LH)	Broken	177.70 FL	*177.70 FL
69	1		*FRONT WHEEL HUB AND BEARING	Damaged	763.80 FL	*763.80 FL
70	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	637.50 FL	*637.50 FL
71	1		*FRONT SHOCK ABSORBER (LH)	Distorted	401.80 FL	*401.80 FL
72	1		*ABSORBER TOP MOUNTING	Not Necessary	196.20 FL	*- FL
73	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,764.00 FL	*- FL
74	1		*RACK & PINION ASSY	Not Necessary	1,634.90 FL	*- FL
75	1		*BAR ,STABILIZER	Not Necessary	360.00 FL	*- FL
76	1		*LINK ASSY ,FRONT STABILIZER LH	Not Necessary	199.00 FL	*- FL
77	1		*KNUCKLE STEERING LH	Distorted	580.80 FL	*580.80 FL
78	1		*JOINT ASSY ,LOWER BALL FRONT (LH)	Distorted / Damaged	199.98 FL	*199.98 FL
79	1		*END SUB-ASSY ,TIE ROD LH	Not Necessary	159.30 FL	*- FL
80	1		*SENSOR ,SPEED FRONT LH	Not Necessary	446.50 FL	*- FL
81	1		*ENGINE UNDER COVER	Not Necessary	457.20 FL	*- FL
82	1		*ENGINE UNDER COVER FRONT	Not Necessary	288.30 FL	*- FL
83	1		*ENGINE CROSS MEMBER	Not Necessary	2,531.70 FL	*- FL
84	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	*- FS
85	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
86	1		*REAR TYRE (LH)	Serviceable	216.00 FS	*- FS
87	1		*FRONT WINDSCREEN GLASS SEALANT	Not Necessary	40.00 FS	*- FS
88	1		*FRONT WINDSCREEN IU BRACKET	Not Necessary	30.00 FS	*- FS
89	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>41,773.13</b>	<b>19,150.93</b>
<b>- List Item Discount on L Items 20.00/25.00% (S\$)</b>	8,213.23	4,748.98
<b>Total Parts (S\$)</b>	<b>33,559.90</b>	<b>14,401.95</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PABEL BEATING	New	1,800.00	1,000.00
2	SPRAY PAINTING CHARGE	New	1,600.00	900.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
8	RE-SET REAR ABS SYSTEM	New	400.00	0.00
9	REMOVE /REFIX FUEL TANK	New	80.00	0.00
10	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
11	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
12	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
13	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
14	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	60.00
16	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
17	RE-SET FRT ABS SYSTEM	New	200.00	0.00
18	REMOVE/REFIX RADIATOR	New	90.00	0.00
19	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	0.00
20	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>6,840.00</b>	<b>2,680.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >