

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002620/UPA3Q2**Date:** 12/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900234916
Claimant Vehicle No :	SLP7825P	Insured Vehicle No :	SMQ1623C
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	8905467654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP7825P		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRY340063
Reg. Date:	19/06/2017 (Man. Year: 2016)	Chassis No:	MR053REH104560389
Colour:	Black	Odometer:	79657 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,342.95	4,516.97	5,825.98	56.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,370.00	2,900.00	3,470.00	54.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,712.95	7,416.97	9,295.98	55.62
Approved Total (Overridden) (S\$)		6,650.00		
(S\$)	16,712.95	6,650.00	10,062.95	60.21
+ GST 7.00/7.00% (S\$)	1,169.91	465.50	704.41	60.21
Nett Amount (S\$)	17,882.86	7,115.50	10,767.36	60.21
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,917.50		

INSPECTION

Date of Assignment:	22/03/2022	
Date Inspected:	22/03/2022	Inspected At: Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Buckled	793.20 FL	*793.20 FL
2	1		*REAR BOOT COVER EMBLEM (LOGO)	Necessary	50.70 FL	*50.70 FL
3	1		*REAR BOOT COVER EMBLEM (COROLLA)	Necessary	42.00 FL	*42.00 FL
4	1		*REAR BOOT COVER EMBLEM (ALTIS)	Necessary	45.60 FL	*45.60 FL
5	2		*REAR BOOT COVER REFLECTOR L&RH	Cracked	407.40 FL	*407.40 FL
6	2		*REAR BOOT COVER HINGE L&RH	Bent / Twisted	139.80 FL	*139.80 FL
7	1		*REAR BOOT COVER NO PLATE GARNISH (CHROME)	Cracked	242.90 FL	*242.90 FL
8	1		*REAR BOOT COVER LOCK	Bent	399.50 FL	*399.50 FL
9	1		*REAR BOOT COVER LATCH	Not Necessary	52.90 FL	*- FL
10	1		*REAR BOOT COVER W/STRIP	Serviceable	175.80 FL	*- FL
11	2		*REAR LAMP ASSY L&RH	Cracked	783.40 FL	*783.40 FL
12	1		*REAR END PANEL	Badly Dented	670.00 FL	*670.00 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	241.90 FL	*241.90 FL
14	1		*SET REAR END PANEL INNER GARNISH CLIPS	Not Necessary	55.00 FL	*- FL
15	1		*REAR BOOT FLOOR PANEL	Repair	818.10 FL	*- FL
16	1		*REAR SPARE TYRE BOARD	Torn	267.00 FL	*267.00 FL
17	1		*REAR BUMPER FASCIA	Distorted	556.40 FL	*556.40 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	55.00 FL	*55.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	399.50 FL	*395.00 FL
20	2		*REAR BUMPER SIDE RETAINER L&RH	Bent	211.60 FL	*211.60 FL
21	1		*REAR BUMPER BRACKET L&RH	Cracked	64.00 FL	*64.00 FL
22	2		*REAR FENDER L&RH	Repair	2,299.60 FL	*- FL
23	2		*REAR FENDER COWLING L&RH	Not Necessary	130.20 FL	*- FL
24	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	55.00 FL	*- FL
25	2		*REAR FENDER INNER GARNISH L&RH	Not Necessary	631.00 FL	*- FL
26	1		*REAR WINDSCREEN GLASS WITH MOULDING	Not Necessary	1,559.20 FL	*- FL
27	1		*ANTENNA ELECTRICAL KEYSensor	Cracked	203.90 FL	*203.90 FL
28	1		*REAR CAMERA	Serviceable	880.00 FS	*- FS
29	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
30	1		*REAR END PANEL SEALER	Necessary	80.00 FS	*50.00 FS
31	1		*REAR BOOT FLOOR INSULATION SHIELD	Not Necessary	380.00 FS	*- FS
32	1		*REAR BUMPER SENSOR	Shorted	380.00 FS	*250.00 FS
33	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,180.60	5,909.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,837.65	1,392.33
Total Parts (\$\$)	10,342.95	4,516.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT RENEW ,KNOCKING & WELDING REAR BOOT COVER ,REAR FENDER L&RH ,REAR BOOT FLOOR PANEL ,REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN REAR CHASSIS & REALIGN BODY	New	2,880.00	1,400.00
2	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	140.00	0.00
3	REMOVE & REFIX REAR BUMPER SENSOR	New	80.00	50.00
4	REMOVE & INSTALL REAR SEATS ,CARPETS ,UPHOLSTERY & ETC	New	280.00	80.00
5	TUFF-KOTE ON DAMAGE PARTS	New	200.00	60.00
6	SPRAY PAINTING ON DAMAGE PARTS	New	2,480.00	1,200.00
7	CHECK ALL LIGHTING AFTER REPAIR	New	60.00	30.00
8	ANTI RUST PROOFING	New	250.00	80.00
Gross Labour Cost (\$)			6,370.00	2,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >