

Thuan

CS3/CI 22062623/uy3

ASSIGNMENT

From

Estimated Cost

OD/TP/WS/TE/RE/DO/RES/EVA/LIN/IV/MV

To Inspect Vehicle No

at Workshop m/c

Insured: SJS 2343D

Policy No DMPCSNW00145932101

Covers No. SNM22D201904/C02/TANKW

Sum Insured:

Excess:

Client's Record

Make of Veh:

Policy Condition

Remarks: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Est. or Market Value: 136k

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. repairs: 4 days Res.: Yes or No

Loss Limit: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted:

Vehicle: IN / OUT

Veh No

Sms981/m

Yr Rogn: 17/2/20

Type: Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier

cc 1998

Colour:

white

NC: Insured / Std / MI / NA

Sp Reading

57129

T/Radio: Insured / Std / MI / NA

Eng/No:

C/No:

STE2B36H903005430

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

NII / S/Rlm / STD A/Rlm or

Tyre Size:

F: 235/55R18

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ecopia

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/3/22

D.O.I.

22/3/22

1600

Survey held at

Garage 13

Des. of Damages:

Front

Rear

O/S / N/S / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

mv: 136k

rchak: 55932

rvj: 80068

rr: 3h-4k

28/3/22

Submit PRS, repair range \$3,000-\$4,000

Date/Time, File Pass 107

☐

: Proff. Report

U6

☐

: Final Report

Date/Time, File Return 107

28/3/22-typist

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

☐

: V/S&I and (\$

Survey Fee:

Transportation:

S + RS: \$

Finish

Delivery

Total