

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 3767R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,362.45	-
2	REAR BUMPER PDC SENSOR @\$281.22 (CONSISTENT)	SERVICEABLE	562.44	-
1	REAR BUMPER DISFUSER (CONSISTENT)	DEFORMED	641.55	641.55
1	REAR BUMPER CHROME MOULDING -CTR (CONSISTENT)	SCRATCHED	190.63	190.63
2	REAR BUMPER CHROME MOULDING-RH/LH @\$110.63 (CONSISTENT)	NECESSARY	221.26	221.26
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	791.65	-
1	REAR BUMPER TOP GUIDE -CTR (CONSISTENT)	NOT NECESSARY	131.50	-
2	REAR BUMPER SIDE GUIDE -RH/LH @\$89.95 (CONSISTENT)	NOT NECESSARY	179.90	-
2	REAR BUMPER LICENCE LAMPS @\$42.20 (CONSISTENT)	SERVICEABLE	84.40	-
	LESS 5% DISCOUNT		-208.29	-52.67
			3,957.49	1,000.77
	SPECIAL NETT ITEMS			
1	SET REAR NO PLATE WITH HOLDER (SN) (CONSISTENT)	BENT	65.00	40.00
			65.00	40.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		40.00	20.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.	NOT NECESSARY	120.00	-
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS.		600.00	250.00
	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		500.00	200.00
			1,260.00	470.00
	GRAND TOTAL		5,282.49	1,510.77

Report Ref No. CC4/ASM22002626/Upa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,200.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM22002626/Upa3q2

CHUA KANG SENG

**Licensed Appraiser**