

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002631/AVY3Q2**Date:** 26/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00118162102

Claimant Vehicle No : SMR4811B **Insured Vehicle No :** GBG2499X

Date of Loss: 17/03/2022 Nature of Claim: TP Claim No: SNM22D201886/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR4811B**

Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: 1NZR788159

Reg. Date: 08/01/2020 (Man. Year: 2019) Chassis No: NHP1707174269

Colour: White Odometer: 59046 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/40 R17 Rear Tyre Size: 215/40 R17

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,971.20	2,127.27	843.93	28.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	930.00	400.00	30.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,301.20	3,057.27	1,243.93	28.92
Approved Total (Overridden) (\$\$)		2,400.00		
(\$\$)	4,301.20	2,400.00	1,901.20	44.20
+ GST 7.00/7.00% (\$\$)	301.08	168.00	133.08	44.20
Nett Amount (\$\$)	4,602.28	2,568.00	2,034.28	44.20

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 22/03/2022 Inspected At: Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 May 2022)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR4811B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR SIDE MIRROR LH	Distorted	1,157.70 FL	*1,157.70 FL
2	1		*FRT DOOR SIDE MIRROR OUTER COVER LH	Cracked	106.20 FL	*106.20 FL
3	1		*FRT DOOR LH	Repair	955.80 FL	*- FL
4	1		*FRT DOOR BLACK TAPE LH	Not Necessary	76.10 FL	*- FL
5	1		*FRT FENDER LH	Dented	602.20 FL	*602.20 FL
6	1		*FRT FENDER HYBRID EMBLEM LH	Necessary	63.60 FL	*63.60 FL
7	1		*FRT SMALL GLASS MIRROR LH	Missing	80.00 FS	*80.00 FS
8	1		*SET FRT DOOR STICKER LH	Necessary	200.00 FS	*150.00 FS
9	1		*FRT FENDER CHROME LH	Necessary	100.00 FS	*80.00 FS
10	1		*QUARTER GARNISH	Cut	250.00 FS	*250.00 FS
11	1		*A PILLAR GARNISH	Cut	120.00 FS	*120.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	3,711.60 2,609.70
					- List Item Discount on L Items 25.00/25.00% (S\$)	740.40 482.43
					Total Parts (S\$)	2,971.20 2,127.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING /WELDING WORKS	New	500.00	400.00
2	TO SPRAY PAINTING	New	700.00	500.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REPLACE STICKER	New	80.00	0.00
Gross Labour Cost (\$)			1,330.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >