



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 6011E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	DENTED	1,218.00	789.00
1	HEADLAMP	BROKEN	2,729.00	2,729.00
1	HEADLAMP TOP PANEL	TO REPAIR SEE LABOUR	271.00	-
1	FRONT BUMPER	BROKEN	1,719.00	1,468.00
2	FRONT BUMPER SIDE RETAINER LH/RH @\$231.00	BROKEN (1 PC ONLY)	462.00	105.00
1	FOG LAMP OUTER CHROME LH	CUT	371.00	220.00
1	CENTER GRILLE	NOT NECESSARY	1,218.00	-
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	SUPPRT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,997.00	-1,327.75
			5,991.00	3,983.25
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	30.00
1	CENTER GRILLE CLIPS (SN)	NOT NECESSARY	25.00	-
1	RADIATOR TOP GARNISH CLIPS (SN)	NOT NECESSARY	35.00	-
1	FRONT FENDER SHIELD CLIPS (SN)	NOT NECESSARY	25.00	-
1	FRONT REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			320.00	30.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF HEADLAMP TOP PANEL,BONNET AND SUPPRT PANEL.		1,000.00	400.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,000.00	600.00
	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		90.00	30.00

Report Ref No. CS/INC22002636/Evy3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREA.		60.00	30.00
	TO REMOVE AND REPLACE FRONT REVERSE SENSOR.		100.00	30.00
	TO REMOVE,REPLACE AND FOCUS HEADLAMP BEAM.		60.00	30.00
			2,310.00	1,120.00
GRAND TOTAL			8,621.00	5,133.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,100.00

Report Ref No. CS/INC22002636/Evy3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.