

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22002639/RPA3Q2**Date:** 06/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100221785-19
Claimant Vehicle No :	SHB5925T	Insured Vehicle No :	SDR3396X
Date of Loss:	18/03/2022	Nature of Claim:	TP
		Claim No:	4372514945SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5925T		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G87272
Reg. Date:	01/12/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU703091765
Colour:	Maroon	Odometer:	140486 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,056.00	0.00	4,056.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,812.00	700.00	1,112.00	61.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,868.00	700.00	5,168.00	88.07
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$73.00/day) (S\$)		292.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,199.00		

INSPECTION

Date of Assignment:	21/03/2022	
Date Inspected:	21/03/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PAD ,RR BUMPER ,RH & LH ,1	Not Necessary	4.00 F	*- F
2	2		*PAD ,RR BUMPER ,RH & LH ,2	Not Necessary	4.00 F	*- F
3	2		*PAD ,RR BUMPER ,RH & LH ,3	Not Necessary	4.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	332.70 F	*- F
5	1		*LINER ,REAR FENDER ,LH	Not Necessary	139.80 F	*- F
6	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
7	1		*LENS & BODY ,REAR COMBINATION ,NO.2	Not Necessary	261.00 F	*- F
8	1		*LAMP ASSY ,REAR LH	Not Necessary	293.60 F	*- F
9	1		*ANTENNA ELECTRICAL KEY	Not Necessary	72.00 F	*- F
10	1		*CLIPS PIECE ,FRT & RR BUMPER	Not Necessary	4.50 F	*- F
11	1		*GUARD ,REAR BUMPER ,LOWER	Not Necessary	374.50 F	*- F
12	1		*COVER ,GUARD RR BUMPER LOWER	Not Necessary	22.00 F	*- F
13	1		*REAR BUMPER REFLECTOR ASSY ,REFLEX ,LH	Not Necessary	39.00 F	*- F
14	1		*COVER ,REAR FLOOR UNDER ,LH	Not Necessary	241.90 F	*- F
15	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Not Necessary	339.60 F	*- F
16	1		*COVER REAR COMBINATION LAMP ,LH	Not Necessary	69.90 F	*- F
17	1		*RETAINER ,RR BUMPER ,LH	Not Necessary	132.60 F	*- F
18	1		*SEAL ,RR BUMPER ,LH	Not Necessary	118.30 F	*- F
19	1		*PAD ,RR BUMPER ,CTR	Not Necessary	11.00 F	*- F
20	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
21	1		*SOCKET & WIRE SUB-ASSY REAR COMBINATION LAMP	Not Necessary	52.30 F	*- F
22	1		*COVER ,RR BUMPER ,CTR	Repair	485.60 F	*- F
23	1		*PANEL SUB-ASSY ,FENDER REAR LH	Repair	871.50 F	*- F

F=Franchise part.

Total Parts (S\$) **4,056.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	300.00
2	SPRAY PAINT	New	756.00	400.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
Gross Labour Cost (\$)			1,812.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >