LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002640/VTY3E2

20/05/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00053992104

Claimant Vehicle

SLD2372A

No:

No:

Insured Vehicle GBG1101A

Date of Loss: 13/03/2022 Nature of Claim: TP

Claim No:

SNM22D201757/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLD2372A Reg No:

Make & Model: VOLKSWAGEN PASSAT, 1.4 TSI (B7) (A)

09/06/2016 (Man. Year: 2016)

Chassis No: Odometer:

Engine No:

CJS154469 WVWZZZ3CZGE202240

56795 km

Reg. Date: Colour:

Brown

Engine Capacity: 1798 cc Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Right Side:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: Nο

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/55 R17 Pirelli 6 mm Pirelli 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/55 R17 Pirelli 6 mm

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,326.70	2,151.00	8,175.70	79.17
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,680.00	460.00	1,220.00	72.62
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,006.70	2,611.00	9,395.70	78.25
	Approved Total (Overridden) (S\$)		2,100.00		
	(S\$)	12,006.70	2,100.00	9,906.70	82.51
	+ GST 7.00/7.00% (S\$)	840.47	147.00	693.47	82.51
	Nett Amount (S\$)	12,847.17	2,247.00	10,600.17	82.51

INSPECTION

Adjuster:

Date of Assignment: 17/05/2022

Date Inspected:

24/03/2022 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ) 29 Ubi Road 4, Dickson Auto Centre

Singapore 408619

Estimated Period of Repair:

3.0 days

Thevan Thomas Karthikesavan

Manager:

DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 May 2022)

(Unsubmitted, no print-code for SLD2372A)

Parts: 143 VOLKSWAGEN PASSAT 1.4 TSI (B7) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) Print Code:

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Cut	1,999.60 F	*1,360.00 FL
10		*REAR BUMPER CLIPS	Necessary	101.20 F	*50.00 FL
2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	199.58 F	*- FL
2		*REAR BUMPER REFLECTOR LH & RH INNER	Serviceable	267.40 F	*- FL
2		*REAR BUMPER REFLECTOR LH & RH OUTER	Serviceable	267.40 F	*- FL
2		*REAR BUMPER CHROME MOULDING LH & RH	Necessary	799.40 F	*653.00 FL
1		*REAR BUMPER CHROME MOULDING CENTRE	Bent	499.70 F	*327.00 FL
1		*REAR BUMPER REINFORCEMENT	Serviceable	1,007.60 F	*- FL
4		*REAR BUMPER REVERSE SENSOR	Serviceable	1,197.48 F	*- FL
1		*REAR END PANEL	Serviceable	1,679.70 F	*- FL
1		*REAR TRUNK	Serviceable	233.69 F	*- FL
1		*REAR TRUNK LOGO	Serviceable	238.60 F	*- FL
1		*REAR TRUNK PASSAT LOGO	Serviceable	200.80 F	*- FL
1		*REAR TRUNK 330TSI LOGO	Serviceable	200.80 F	*- FL
1		*REAR TRUNK INNER LOCK	Serviceable	1,433.75 F	*- FL
anchise	part. L=ListIte	emDisc.	_		
			Sub Total (S\$)	10,326.70	2,390.00
- List Item Discount on L Items 0.00/10.00% (S\$)			0.00	239.00	
			Total Parts (S\$)	10,326.70	2,151.00
	1 10 2 2 2 2 1 1 4 1 1 1 1 1	10 2 2 2 2 2 1 1 1 4 1 1 1 1	1 *REAR BUMPER 10 *REAR BUMPER CLIPS 2 *REAR BUMPER SIDE RETAINER LH & RH 2 *REAR BUMPER REFLECTOR LH & RH INNER 2 *REAR BUMPER REFLECTOR LH & RH OUTER 2 *REAR BUMPER CHROME MOULDING LH & RH 1 *REAR BUMPER CHROME MOULDING CENTRE 1 *REAR BUMPER REINFORCEMENT 4 *REAR BUMPER REVERSE SENSOR 1 *REAR END PANEL 1 *REAR TRUNK 1 *REAR TRUNK LOGO 1 *REAR TRUNK 330TSI LOGO 1 *REAR TRUNK INNER LOCK anchise part. L=ListItemDisc.	1 *REAR BUMPER CLIPS Necessary 2 *REAR BUMPER SIDE RETAINER LH & RH Serviceable 2 *REAR BUMPER REFLECTOR LH & RH INNER Serviceable 2 *REAR BUMPER REFLECTOR LH & RH OUTER Serviceable 2 *REAR BUMPER CHROME MOULDING LH & RH Necessary 1 *REAR BUMPER CHROME MOULDING CENTRE Bent 1 *REAR BUMPER REINFORCEMENT Serviceable 4 *REAR BUMPER REVERSE SENSOR Serviceable 1 *REAR BUMPER REVERSE SENSOR Serviceable 1 *REAR TRUNK Serviceable 1 *REAR TRUNK Serviceable 1 *REAR TRUNK LOGO Serviceable 1 *REAR TRUNK LOGO Serviceable 1 *REAR TRUNK PASSAT LOGO Serviceable 1 *REAR TRUNK 330TSI LOGO Serviceable 1 *REAR TRUNK SOGO Serviceable 1 *REAR TRUNK INNER LOCK Serviceable 2 *REAR TRUNK INNER LOCK Serviceable 3 *REAR TRUNK INNER LOCK Serviceable 4 *REAR TRUNK INNER LOCK Serviceable 5 **CLIST Item Discount on L Items 0.00/10.00% (S\$)	1 *REAR BUMPER Cut 1,999.60 F 10 *REAR BUMPER CLIPS Necessary 101.20 F 2 *REAR BUMPER SIDE RETAINER LH & RH Serviceable 199.58 F 2 *REAR BUMPER REFLECTOR LH & RH INNER Serviceable 267.40 F 2 *REAR BUMPER REFLECTOR LH & RH OUTER Serviceable 267.40 F 2 *REAR BUMPER CHROME MOULDING LH & RH Necessary 799.40 F 1 *REAR BUMPER CHROME MOULDING CENTRE Bent 499.70 F 1 *REAR BUMPER REINFORCEMENT Serviceable 1,007.60 F 4 *REAR BUMPER REVERSE SENSOR Serviceable 1,197.48 F 1 *REAR END PANEL Serviceable 233.69 F 1 *REAR TRUNK Serviceable 233.69 F 1 *REAR TRUNK LOGO Serviceable 238.60 F 1 *REAR TRUNK ASSAT LOGO Serviceable 200.80 F 1 *REAR TRUNK ASSAT LOGO Serviceable 200.80 F 1 *REAR TRUNK ASSAT LOGO Serviceable 200.80 F 1<

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE & REFIX ALL WIRING, DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING	New	80.00	30.00
2	TO DO DIANOSTIC SCANNING AND RESET SYSTEM	New	200.00	0.00
3	TO REMOVE & REFIT REVERSE SENSORS	New	200.00	30.00
4	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS. PANEL BEAT, CUT & WELD IN PLACE NEW PARTS & PANELS WITH FULL ALIGNMENT	New	600.00	200.00
5	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE & PAINT ALL NEW PARTS & PANELS	New	600.00	200.00
	Gross Labour Cost (S\$)		1,680.00	460.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >