

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002642/RVY3N2**Date:** 04/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00025032200	
Claimant Vehicle No :	SMY8738S	Insured Vehicle No :	SMU4588E	
Date of Loss:	17/03/2022	Nature of Claim:	TP	Claim No: SNM22D201918/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY8738S		Engine No:	P520727191
Make & Model:	MAZDA 3, 1.5 (A)		Chassis No:	JM6BP2SAAM1107112
Reg. Date:	29/03/2021 (Man. Year: 2021)		Odometer:	76407 km
Colour:	Blue			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,450.00	832.92	3,617.08	81.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	660.00	1,010.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,120.00	1,492.92	4,627.08	75.61
Approved Total (Overridden) (\$\$)		1,200.00		
Nett Amount (\$\$)	6,120.00	1,200.00	4,920.00	80.39

INSPECTION

Date of Assignment:	28/03/2022	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE Singapore 575721
Date Inspected:	23/03/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY8738S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,600.00 F	*997.40 FL
2	1		*REAR END PANEL	Not Necessary	1,600.00 F	*- FL
3	1		*REAR BOOT LOCK	Not Necessary	500.00 F	*- FL
4	1		*REAR BUMPER SENSOR	Not Necessary	300.00 F	*- FL
5	1		*REVERSE CAMERA	Not Necessary	250.00 F	*- FL
6	1		*REAR CARPLATE LIGHT	Not Necessary	120.00 F	*- FL
7	1		*CARPLATE }	Cracked	50.00 FS	*35.00 FS
8	1		*CARPLATE HOLDER }	Cracked	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,450.00	1,032.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	199.48
Total Parts (\$\$)	4,450.00	832.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIT REAR PANEL	New	600.00	200.00
2	REMOVE,REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	60.00
3	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	0.00
4	TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	0.00
5	TO RESPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$\$)			1,670.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >