

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22002645/AVY3Q2**Date:** 10/01/2023**REFERENCE****Insured/Claimant:** LIM KAY CHUAN **Policy No:** DMPCSNW00210202100**Date of Loss:** 10/03/2022 **Nature of Claim:** OD **Claim No:** SNM22D201709/C01/TANCHC**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: SCZ3338J
Make & Model: MERCEDES-BENZ S400L, 3.0 (A) **Engine No:** 27682430101614
Reg. Date: 15/10/2014 (Man. Year: 2014) **Chassis No:** WDD2221652A106401
Colour: Brown **Odometer:** 109997 km
Engine Capacity: 2996 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 245/45 R19 **Rear Tyre Size:** 245/45 R19
Front Left Side: Goodyear 6 mm **Rear Left Side:** Goodyear 6 mm
Front Right Side: Goodyear 6 mm **Rear Right Side:** Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,686.80	19,464.40	42,222.40	68.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,960.00	4,780.00	3,180.00	39.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	69,646.80	24,244.40	45,402.40	65.19
Approved Total (Overridden) (\$\$)		19,300.00		
- Excess (\$\$)	1,000.00	1,000.00	0.00	0.00
(\$\$)	68,646.80	18,300.00	50,346.80	73.34
+ GST 7.00/7.00% (\$\$)	4,805.28	1,281.00	3,524.28	73.34
Nett Amount (\$\$)	73,452.08	19,581.00	53,871.08	73.34

INSPECTION**Date of Assignment:** 25/03/2022**Date Inspected:** 22/03/2022 **Inspected At:**

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 14.0 days**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	143	MERCEDES-BENZ S400L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCZ3338J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Dented	3,480.00 F	*1,680.00 F
2	2		*BONNET LOCK (WCP)	Not Necessary	86.00 F	*- F
3	2		*BONNET HINGES -LH & RH (WCP)	Not Necessary	596.00 F	*- F
4	2		*BONNET DAMPER -LH & RH (WCP)	Not Necessary	118.00 F	*- F
5	1		*BONNET INSULATOR (WCP)	Not Necessary	245.00 F	*- F
6	1		*FRONT GRILLE (WCP)	Cracked	795.00 F	*385.00 F
7	1		*BONNET STAR (WCP)	Damaged	115.00 F	*51.00 F
8	1		*FRONT BUMPER (WCP)	Repair	2,105.00 F	*- F
9	1		*FRONT WINDSCREEN (WCP)	Shattered	2,390.00 F	*1,368.00 F
10	1		*SET WIPER BLADE (WCP)	Cut	168.00 F	*100.00 F
11	1		*ROOF PANEL (WCP)	Repair	2,475.00 F	*- F
12	2		*ROOF PANEL MOULDING -LH & RH (WCP)	Repair	710.00 F	*- F
13	1		*FRONT WINDSCREEN PILLAR -RH (WCP)	Dented	8,618.00 F	*596.00 F
14	1		*FRONT FENDER -RH (WCP)	Repair	1,388.00 F	*- F
15	1		*FRONT DOOR -RH (WCP)	Dented	3,496.00 F	*1,755.00 F
16	1		*FRONT DOOR GLASS MOULDING (CHROME) (WCP)	Dented	345.00 F	*161.00 F
17	1		*FRONT DOOR OUTER CHROME MOULDING -RH (WCP)	Cut	260.00 F	*95.00 F
18	1		*FRONT WING MIRROR -RH (WCP)	Cracked	1,090.00 F	*485.00 F
19	1		*FRONT WING MIRROR GLASS-RH (WCP)	Cracked	1,060.00 F	*510.00 F
20	1		*REAR DOOR -RH (WCP)	Distorted	3,690.00 F	*1,805.00 F
21	1		*REAR WINDSCREEN GLASS -RH (WCP)	Shattered	980.00 F	*468.00 F
22	1		*REAR QUARTER GLASS -RH (WCP)	Shattered	488.00 F	*208.00 F
23	1		*REAR DOOR GLASS OUTER MOULDING (CHROME) -RH (WCP)	Cut	448.00 F	*218.00 F
24	1		*REAR DOOR OUTER CHROME MOULDING -RH (WCP)	Dented	195.00 F	*84.00 F
25	1		*REAR DOOR CHANNEL -RH (WCP)	Distorted	360.00 F	*220.00 F
26	1		*REAR DOOR OUTER HANDLE -RH (WCP)	Not Necessary	798.00 F	*- F
27	1		*ROOF PANEL PILLAR -RH (WCP)	Repair	1,266.00 F	*- F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR FENDER PILLAR -RH (WCP)	Repair	1,889.00 F	*- F
29	1		*REAR DOOR CURTAIN -RH (WCP)	Cut	1,994.00 F	*975.00 F
30	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*45.00 FS
31	1		*FRONT WING MIRROR SIGNAL LAMP -RH (WCP)	Cracked	240.00 F	*180.00 F
32	1		*HEAD LAMP -RH (WCP)	Cracked	3,800.00 F	*2,500.00 F
33	1		*FRONT DOOR BLACK GARNISH -RH (WCP)	Cut	480.00 F	*200.00 F
34	1		*REAR DOOR BLACK GARNISH -RH (WCP)	Distorted	440.00 F	*200.00 F
35	1		*REAR DOOR INNER TRIM BOARD -RH (WCP)	Cut	3,410.00 F	*1,500.00 F
36	1		*REAR DOOR INNER TRIM BOARD CLIPS-RH (WCP)	Necessary	60.00 F	*30.00 F
37	1		*ROOF PANEL INNER TRIM BOARD (WCP)	Stained	5,880.00 F	*1,800.00 F
38	1		*ROOF PANEL INNER TRIM BOARD CLIPS (WCP)	Necessary	80.00 F	*80.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)				56,083.00	17,699.00
+ Margin on L,N Items 10.00/10.00% (\$\$)				5,603.80	1,765.40
Total Parts (\$\$)				61,686.80	19,464.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT AND RENEW DAMAGE PARTS	New	3,000.00	1,600.00
2	TO PUTTY AND SPRAY UP PAINT WORK	New	2,800.00	2,000.00
3	TO UNDERSEAL	New	150.00	80.00
4	TO CHECK WIRING	New	30.00	30.00
5	TO REMOVE FRONT WINDSCREEN	New	150.00	120.00
6	TO TRANSFER DOOR FITTINGS (FRONT & REAR)	New	300.00	200.00
7	TO REMOVE FRONT & REAR SEATS & UPHOLSTERY	New	280.00	150.00
8	INTERIOR CLEANING	New	450.00	300.00
9	TO REMOVE AND REPLACE ROOF PANEL INNER TRIM BOARD	New	800.00	300.00
Gross Labour Cost (\$\$)			7,960.00	4,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >