

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22002647/EQY3N2**Date:** 12/05/2022REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SNB8316K**Insured Vehicle No :** SKS9800T

Date of Loss: 18/03/2022

Nature of Claim: TP

Claim No: DMPC2200111H

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNB8316K**

Make & Model: BMW X1 SDRIVE18I, 1.5 X LINE LED HL (A)

Engine No: 36226481B38A15F

Reg. Date: 16/09/2021 (Man. Year: 2021)

Chassis No: WBA32AA0005U03813

Colour: White

Odometer: 6556 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R18

Rear Tyre Size: 225/50R18

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,292.50	2,291.70	2,000.80	46.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,613.00	3,822.00	2,791.00	42.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,905.50	6,113.70	4,791.80	43.94
+ GST 7.00/7.00% (S\$)	763.39	427.96	335.43	43.94
Nett Amount (S\$)	11,668.89	6,541.66	5,127.23	43.94

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 28/03/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 May 2022)

Parts: M1-SUV BMW X1 SDRIVE18I 1.5 X LINE LED HL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB8316K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,279.75 FS	*- FS
2	1		*REAR BUMPER TRIM PANEL (X LINE)	Crushed	223.60 FS	*223.60 FS
3	1		*RR BUMPER CARRIER	Dented	516.00 FS	*516.00 FS
4	1		*MOUNTING SMART OPENER	Broken	46.35 FS	*46.35 FS
5	1		*REAR TRIM UNDERRIDE PROTECTION (X L)	Crushed	148.90 FS	*148.90 FS
6	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	145.20 FS	*- FS
7	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	145.20 FS	*- FS
8	1		*REAR BUMPER PANEL PRIMED	Crushed	894.35 FS	*894.35 FS
9	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Crushed	262.95 FS	*262.95 FS
10	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	61.80 FS	*- FS
11	1		*BOOTLID SEALING	Not Necessary	167.30 FS	*- FS
12	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*- FS
13	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
14	1		*TAILPIPE TRIM BRIGHT CHROME	Cut	119.55 FS	*119.55 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **4,292.50** **2,291.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND TAILGATE	New	2,550.00	1,275.00
2	TO RESPRAY REAR BUMPER AND TAILGATE	New	2,328.00	2,211.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
6	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	0.00
7	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
9	TO SUPPLY REAR EMBOSS NUMBER PLATE	New	83.00	0.00
Gross Labour Cost (\$\$)			6,613.00	3,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >