

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002648/KVY3E2

Date: 20/06/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00073352103  
Claimant Vehicle No: SKS9119C Insured Vehicle No: GBF915E  
Date of Loss: 19/03/2022 Nature of Claim: TP Claim No: SNM22D201954/C02/LEEPG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS9119C  
Make & Model: TOYOTA CAMRY, 2.0 (A) Engine No: 1AZE294749  
Reg. Date: 03/02/2015 (Man. Year: 2014) Chassis No: MR053BK5104024953  
Colour: Metallic Gold Odometer: 63531 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,227.00	1,057.00	170.00	13.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	830.00	300.00	26.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,357.00</b>	<b>1,887.00</b>	<b>470.00</b>	<b>19.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>(S\$)</b>	2,357.00	1,650.00	707.00	30.00
<b>+ GST 7.00/7.00% (S\$)</b>	164.99	115.50	49.49	30.00
<b>Nett Amount (S\$)</b>	<b>2,521.99</b>	<b>1,765.50</b>	<b>756.49</b>	<b>30.00</b>

### INSPECTION

Date of Assignment: 24/03/2022  
Date Inspected: 13/04/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761  
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2022)
Parts:	143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS9119C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	180.00 F	*180.00 F
2	1		*FRONT BUMPER REINFORCEMENT	Repair	130.00 F	*- F
3	1		*FRONT BUMPER SPONGE	Serviceable	40.00 F	*- F
4	1		*FRONT BUMPER LH SIDE RETAINER	Cracked	50.00 F	*50.00 F
5	6		*FRONT BUMPER CLIPS	Necessary	12.00 F	*12.00 F
6	1		*LH HEADLAMP	Cut	390.00 F	*390.00 F
7	1		*FRONT LH CORNAL PARKING SENSOR	Shorted	145.00 F	*145.00 F
8	1		*FRONT LH FENDER	Bent	160.00 F	*160.00 F
9	1		*FRONT LH FENDER INNER SHIELD	Distorted	85.00 F	*85.00 F
10	5		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	10.00 F	*10.00 F
11	1		*FRONT LH FENDER EMBLEM (VVTI)	Necessary	25.00 F	*25.00 F
Total Parts (S\$)						1,227.00 1,057.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX FRT BUMPER ASSY, FOG LAMPS, HEADLAMP, FRT LH FENDER, TO KNOCK & REPAIR FRT LH FENDER INNER PANEL, FRT SUPPORT PANEL AND REALIGN THE SAME	New	500.00	400.00
2	PUTTY & RESPRAY ON FRT BUMPER, REINFORCEMENT, FRT LH FENDER	New	600.00	400.00
3	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,130.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >