

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22002649/APA3Q2**Date:** 18/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100436867
<b>Claimant Vehicle No :</b>	SDR6969Z	<b>Insured Vehicle No :</b>	SKW6383D
Date of Loss:	19/03/2022	Nature of Claim:	TP
		Claim No:	3478977156SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDR6969Z</b>		
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Engine No:	27191031351467
Reg. Date:	20/02/2012 (Man. Year: 2011)	Chassis No:	WDD2040452A661076
Colour:	White	Odometer:	151310 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,410.00	1,066.50	343.50	24.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	100.00	100.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,610.00</b>	<b>1,166.50</b>	<b>443.50</b>	<b>27.55</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,610.00</b>	<b>900.00</b>	<b>710.00</b>	<b>44.10</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment:	22/03/2022	
Date Inspected:	22/03/2022	Inspected At: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	1.0 days	

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR WING MIRROR	Damaged	985.00 F	*985.00 FL
2	1		*FRONT DOOR WING MIRROR GLASS	Not Necessary	245.00 F	*- FL
3	1		*FRONT DOR WING MIRROR COVER	Cut	180.00 FS	*180.00 FS
					Sub Total (\$\$)	1,410.00 1,165.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 98.50
					Total Parts (\$\$)	1,410.00 1,066.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	200.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>200.00</b>	<b>100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >