

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002651/AEA3Q2**Date:** 08/09/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070171775
Claimant Vehicle No :	SJM8290P	Insured Vehicle No :	SDK4993C
Date of Loss:	23/01/2022	Nature of Claim:	TP
		Claim No:	6761863051SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM8290P	Engine No:	27186030047989
Make & Model:	MERCEDES-BENZ E200, 1.8 CGI (A)	Chassis No:	WDD2073482F041029
Reg. Date:	24/05/2010 (Man. Year: 2010)	Odometer:	71634 km
Colour:	Silver		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,088.70	4,893.00	7,195.70	59.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	730.00	1,330.00	64.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,148.70	5,623.00	8,525.70	60.26
Approved Total (Overridden) (S\$)		4,500.00		
Nett Amount (S\$)	14,148.70	4,500.00	9,648.70	68.19
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,836.45		

INSPECTION

Date of Assignment:	23/03/2022	Sin Yu Sin Workshop (HQ)
Date Inspected:	23/03/2022 Inspected At:	1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit)
Estimated Period of Repair:	3.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	2,246.00 FL	*- FL
2	1		*FRONT BONNET LOGO	Necessary	85.00 FL	*85.00 FL
3	1		*FRONT BONNET CHROME	Not Necessary	188.00 FL	*- FL
4	1		*FRONT HEADLAMP L/R	N/s Cracked	4,770.00 FL	*2,385.00 FL
5	2		*FRONT HEADLAMP TOP GARNISH L/R	Not Necessary	120.00 FL	*- FL
6	2		*FRONT HEADLAMP NOZZLE L/R	Not Necessary	360.00 FL	*- FL
7	2		*FRONT HEADLAMP NOZZLE COVER L/R	Not Necessary	130.00 FL	*- FL
8	1		*FRONT BUMPER	Torn	1,450.00 FL	*1,450.00 FL
9	1		*FRONT BUMPER NO PLATE GARNISH	Deformed	155.00 FL	*155.00 FL
10	1		*FRONT BUMPER TOWING COVER	Not Necessary	52.00 FL	*- FL
11	2		*FRONT BUMPER LOWER CHROME L/R	Necessary	340.00 FL	*340.00 FL
12	1		*FRONT BUMPER LOWER CHROME CENTRE	Necessary	210.00 FL	*210.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	85.00 FL	*- FL
14	4		*FRONT PARKING SENSOR	Not Necessary	1,120.00 FL	*- FL
15	4		*FRONT PARKING SENSOR HOLDER	Not Necessary	160.00 FL	*- FL
16	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	116.00 FL	*- FL
17	1		*FRONT BUMPER INNER SPONGE	Cracked	140.00 FL	*140.00 FL
18	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	576.00 FL	*- FL
19	1		*BRACE PANEL	Not Necessary	130.00 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	135.00 FL	*- FL
21	1		*FRONT GRILLE	Cracked	425.00 FL	*425.00 FL
22	1		*FRONT GRILLE LOGO BASE	Not Necessary	170.00 FL	*- FL
23	1		*FRONT GRILLE LOGO EMBLEM	Necessary	130.00 FL	*130.00 FL
24	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
25	1		*FRONT NUMBER PLATE GARNISH	Deformed	50.00 FS	*30.00 FS
26	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,418.00	5,425.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,329.30	532.00
Total Parts (\$\$)	12,088.70	4,893.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RECTIFY ELECTRICAL FAULTS WHERE NECESSARY	New	60.00	30.00
2	TO STRAIGHTEN,REPAIR,REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	300.00
3	TO SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,060.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >