

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22002653/RGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKX7986C **Insured Vehicle No :** SML8732B

Date of Loss: 16/03/2022 Nature of Claim: TP Claim No: MFL2022D0001555

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7986C**

Make & Model: PEUGEOT 308, 1.2 SW ALLURE PURETECH 2WD S/R. (A) Engine No: 10WAVB0871818

Reg. Date: 29/12/2015 (Man. Year: 2015) Chassis No: VF3LPHNYWFS263446

Colour: Grey Odometer: 115867 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,438.50	11,944.00	7,494.50	38.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,690.00	1,320.00	43.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,448.50	13,634.00	8,814.50	39.27
Approved Total (Overridden) (\$\$)		10,900.00		
(\$\$)	22,448.50	10,900.00	11,548.50	51.44
+ GST 7.00/7.00% (\$\$)	1,571.40	763.00	808.40	51.44
Nett Amount (\$\$)	24,019.90	11,663.00	12,356.90	51.44
+ Car Rental (8.0 x S\$100.00/day) (\$\$)		800.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		12,470.45		

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 23/03/2022 Inspected At:

CYS Automobile Services Pte Ltd (Woodlands)
38 Woodlands Industrial Park East 1, #07-17,
Admiralty Industrial Park
Singapore 757700

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 May 2022)	
Parts:	N/A	PEUGEOT 308 1.2 SW ALLURE PURETECH 2WD S/R. (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX7986C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET EMBLEM	Not Necessary	60.00 FL	*- FL
2	2		*HEADLAMP ASSY	Cracked	5,100.00 FL	*5,100.00 FL
3	1		*FRONT GRILLE	Cracked	350.00 FL	*350.00 FL
4	1		*FRONT GRILLE CHROME	Cracked	560.00 FL	*560.00 FL
5	1		*FRONT BUMPER	Cracked	1,480.00 FL	*1,480.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	480.00 FL	*480.00 FL
7	1		*FRONT BUMPER LOWER GRILLE CHROME	Not Necessary	530.00 FL	*- FL
8	1		*FRONT BUMPER PAD	Not Necessary	380.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	680.00 FL	*- FL
10	1		*FRONT BUMPER SPONGE	Not Necessary	240.00 FL	*- FL
11	6		*FRONT BUMPER PARKING SENSOR	Not Necessary	2,100.00 FL	*- FL
12	1		*FRONT SUPPORT PANEL	Cracked	1,200.00 FL	*1,200.00 FL
13	1		*TAILGATE PEUGEOT EMBLEM	Not Necessary	220.00 FL	*- FL
14	1		*TAILGATE 308 EMBLEM	Not Necessary	210.00 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Not Necessary	390.00 FL	*- FL
16	1		*REAR BUMPER	Deformed	1,600.00 FL	*1,600.00 FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	650.00 FL	*650.00 FL
18	1		*REAR BUMPER TOWING COVER	Not Necessary	85.00 FL	*- FL
19	1		*REAR BUMPER PAD	Scratched	350.00 FL	*350.00 FL
20	6		*REAR BUMPER REVERSE SENSOR	Not Necessary	2,040.00 FL	*- FL
21	1		*REAR END PANEL	Repair	950.00 FL	*- FL
22	1		*REAR END PANEL TOP GARNISH	Not Necessary	400.00 FL	*- FL
23	1		*FRONT BUMPER NUMBER PLATE	Bent	45.00 FS	*35.00 FS
24	1		*SET FRONT BUMPER CLIPS	Not Necessary	28.00 FS	*- FS
25	1		*SET REAR BUMPER CLIPS	Necessary	38.00 FS	*38.00 FS
26	1		*FRONT BUMPER SENSOR PROTECTOR	Broken	280.00 FL	*280.00 FL
27	1		*AIR-CON CONDENSER	Cut	550.00 FL	*550.00 FL
28	1		*REAR BUMPER TOP STAY	Broken	200.00 FL	*200.00 FL
29	1		*REAR BUMPER REVERSE MODULE	Cracked	390.00 FL	*390.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,586.00	13,263.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,147.50	1,319.00
Total Parts (\$\$)	19,438.50	11,944.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AIR-CON CONDENSER ,PIPE ,DRIER AND TOP -UP AIR-CON GAS	New	120.00	100.00
2	TO REMOVE AND REFIX REAR FENDER INNER TRIM BOARD & CUSHION SEAT	New	80.00	0.00
3	TO CHECK AND COMPUTER RESET	New	200.00	100.00
4	TO REMOVE AND REFIX REVERSE SENSOR	New	80.00	60.00
5	TO CHECK WIRING FUNCTION	New	30.00	30.00
6	TO APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL	New	100.00	0.00
7	LABOUR CHARGES	New	1,200.00	800.00
8	TO PUTTY AND SPRAY PAINTING CHARGES	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,010.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >