

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002654/BPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700088815
Claimant Vehicle No :	SFW3357J	Insured Vehicle No :	SLU8304T
Date of Loss:	22/03/2022	Nature of Claim:	TP
		Claim No:	8246175387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFW3357J	Engine No:	4A910162502
Make & Model:	MITSUBISHI COLT PLUS, 1.5 (A)	Chassis No:	JMYLTZ23W9Z000448
Reg. Date:	15/10/2010 (Man. Year: 2010)	Odometer:	135545 km
Colour:	Red		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,066.02	7,414.95	9,651.07	56.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,400.00	2,970.00	4,430.00	59.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,466.02	10,384.95	14,081.07	57.55
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	24,466.02	8,300.00	16,166.02	66.08
+ GST 7.00/7.00% (S\$)	1,712.62	581.00	1,131.62	66.08
Nett Amount (S\$)	26,178.64	8,881.00	17,297.64	66.08
+ Car Rental (16.0 x S\$100.00/day + 7.00% GST) (S\$)		1,712.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		10,720.45		
Global Sum Settlement (S\$)		10,700.00		

INSPECTION

Date of Assignment:	23/03/2022	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	23/03/2022 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	14.0 days	Singapore 575722

Adjuster: Lim Teow Guan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	978.00 FL	*835.00 FL
2	1		*TAILGATE LOGO	Necessary	68.00 FL	*42.00 FL
3	1		*TAILGATE WEATHERSTRIP	Torn	281.20 FL	*191.00 FL
4	1		*TAILGATE OUTER GARNISH	Not Damaged	285.00 FL	*- FL
5	1		*TAILGATE INNER HANDLE	Not Damaged	78.00 FL	*- FL
6	1		*TAILGATE INNER LOCK	Jammed	372.00 FL	*372.00 FL
7	1		*TAILGATE LAMP	O/S Broken	974.00 FL	*386.00 FL
8	1		*TAILGATE INNER TRIM BOARD	Broken	449.00 FL	*274.00 FL
9	1		*TAILGATE WINDSCREEN MOULDING TOP	Necessary	147.00 FL	*68.00 FL
10	1		*TAILGATE WINDSCREEN MOULDING BOTTOM	Necessary	79.00 FL	*68.00 FL
11	1		*REAR BUMPER	Broken	891.00 FL	*592.00 FL
12	2		*REAR BUMPER SIDE RETAINER	Necessary	323.80 FL	*122.00 FL
13	2		*REAR BUMPER BRACKET	No such part	285.40 FL	*- FL
14	1		*REAR BUMPER REFLECTOR	O/S Broken	336.00 FL	*27.00 FL
15	1		*REAR END PANEL INNER	Dented	496.00 FL	*296.00 FL
16	1		*REAR END PANEL OUTER	Dented	568.00 FL	*268.00 FL
17	1		*REAR END PANEL TOP GARNISH	Broken	184.00 FL	*166.00 FL
18	1		*REAR END PANEL AIR VENT	Not Damaged	64.00 FL	*- FL
19	1		*SPARE TYRE PANEL	Dented	945.00 FL	*856.00 FL
20	1		*SPARE TYRE PANEL TOP COVER	Not Damaged	385.00 FL	*- FL
21	1		*SPARE TYRE PANEL TRAY	Not Damaged	465.00 FL	*- FL
22	1		*REAR FENDER RH	Dented	748.00 FL	*748.00 FL
23	1		*REAR FENDER INNER TRIM BOARD	O/S Broken	979.46 FL	*179.00 FL
24	1		*REAR FENDER SIDE GLASS MOULDING	Necessary	188.00 FL	*188.00 FL
25	1		*TAILLAMP	O/S Broken	1,172.00 FL	*325.00 FL
26	1		*EXHAUST SILENCER	Bent	862.00 FL	*362.00 FL
27	2		*EXHAUST MOUNTING	Necessary	92.00 FL	*50.00 FL
28	1		*FRONT BUMPER	Broken	983.60 FL	*834.00 FL
29	2		*FRONT BUMPER SIDE RETAINER	Necessary	158.40 FL	*48.00 FL
30	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	598.60 FL	*- FL
31	1		*FRONT BUMPER INNER LOWER GARNISH	Broken	382.60 FL	*176.50 FL
32	1		*FRONT BUMPER LOGO	Necessary	68.00 FL	*32.00 FL
33	1		*FRONT SUPPORT PANEL	Not Damaged	786.30 FL	*- FL
34	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
35	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
36	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
37	1		*TAILGATE LAMP CLIPS	O/S Necessary	100.00 FS	*20.00 FS
38	1		*TAILGATE LAMP INNER SEAL	O/S Necessary	120.00 FS	*20.00 FS
39	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
41	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*20.00 FS
42	1		*TAILGATE WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
43	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
44	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
45	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
46	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
47	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
48	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*30.00 FS
49	1		*REAR FENDER SIDE GLASS SEALANT	Necessary	100.00 FS	*20.00 FS
50	1		*REAR FENDER SIDE GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
51	1		*REAR FENDER SIDE GLASS PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
52	1		*TAILLAMP CLIPS	O/S Necessary	100.00 FS	*20.00 FS
53	1		*TAILLAMP INNER SEAL	O/S Necessary	120.00 FS	*20.00 FS
54	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
55	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

6/30/22, 11:03 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT & REAR NUMBER PLATE W/CASING	Rear Bent	160.00 FS	*30.00 FS
57	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
58	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					18,633.36	8,165.50
- List Item Discount on L Items 10.00/10.00% (\$)					1,567.34	750.55
Total Parts (\$)					17,066.02	7,414.95
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	R&R EXHAUST SILENCER	New	150.00	50.00
5	R&R REAR FENDER SIDE GLASS	New	250.00	60.00
6	REAR UPHOLSTERY	New	300.00	0.00
7	REAR CHECK WIRING	New	100.00	0.00
8	REAR PANEL BEATING	New	1,800.00	1,200.00
9	REAR RUST PROOFING	New	200.00	0.00
10	REAR SPRAY PAINTING	New	1,800.00	1,000.00
11	FRONT UPHOLSTERY	New	200.00	0.00
12	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
13	FRONT CHECK WIRING	New	100.00	0.00
14	FRONT PANEL BEATING	New	800.00	200.00
15	FRONT RUST PROOFING	New	100.00	0.00
16	FRONT SPRAY PAINTING	New	800.00	200.00
Gross Labour Cost (\$\$)			7,400.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >