

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG22002655/AQCE2

**Date:** 24/06/2022

### REFERENCE

Insured/Claimant:	NG LAY HAR (HUANG LIXIA)	Policy No:	1800152412-02	
Date of Loss:	17/03/2022	Nature of Claim:	OD	Claim No: 8296348646SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG5456U		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK071522
Reg. Date:	24/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49KN000657
Colour:	Blue	Odometer:	71792 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,761.00	4,704.56	4,056.44	46.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,452.00	1,602.00	3,850.00	70.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,213.00</b>	<b>6,306.56</b>	<b>7,906.44</b>	<b>55.63</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>13,413.00</b>	<b>5,506.56</b>	<b>7,906.44</b>	<b>58.95</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>938.91</b>	<b>385.46</b>	<b>553.45</b>	<b>58.95</b>
<b>Nett Amount (S\$)</b>	<b>14,351.91</b>	<b>5,892.02</b>	<b>8,459.89</b>	<b>58.95</b>

### INSPECTION

Date of Assignment:	23/03/2022		
Date Inspected:	22/03/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,188.00 FS	*2,550.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Deformed	249.00 FS	*198.80 FS
4	1		*REAR BUMPER SPOILER	Cut	276.00 FS	*220.80 FS
5	1		*REAR BUMPER TRIM	Cracked	326.00 FS	*260.80 FS
6	1		*REAR BUMPER BRACKET - RH	Not Necessary	130.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR - RH	Cracked	46.00 FS	*36.48 FS
8	1		*TAIL LIGHT - RH	Cut	1,135.00 FS	*908.00 FS
9	1		*TAIL LIGHT TRIM - RH	Not Necessary	34.00 FS	*- FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,131.00 FS	*- FS
11	2		*REAR BUMPER REINFORCEMENT SEAL	Not Necessary	32.00 FS	*- FS
12	2		*REAR BUMPER GUIDE SECTION - LH / RH	O/S Cracked	52.00 FS	*20.16 FS
13	1		*REAR BUMPER GUIDE SECTION UPPER - RH	Not Necessary	51.00 FS	*- FS
14	1		*GUIDE SECTION PIN	Not Necessary	3.00 FS	*- FS
15	2		*REAR BUMPER HOLDING STRAP - LH / RH	Not Necessary	188.00 FS	*- FS
16	1		*TELEPHONE AERIAL	Not Necessary	192.00 FS	*- FS
17	1		*REAR PARKING AID SENSOR - INNER / OUTER	Outer Damaged	530.00 FS	*195.12 FS
18	4		*REAR PARKING AID SENSOR SEAL RING	Necessary	10.00 FS	*8.00 FS
19	1		*REAR VENT TRIM	Not Necessary	75.00 FS	*- FS
20	1		*EXHAUST TAIL PIPE - RH	Cut	383.00 FS	*306.00 FS
21	1		*SUNDRIES	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 8,761.00 4,704.56

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. TO INSPECT THE DAMAGES	New	2,100.00	500.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
4	TO RESPRAY REAR BUMPER, RHS TAILLAMP AND REAR END PANELLING	New	2,800.00	550.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,452.00</b>	<b>1,602.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >