

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22002656/KTY3N2**Date:** 29/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00098042101

Claimant Vehicle No : SMX2713H **Insured Vehicle No :** GBE6464E

Date of Loss: 16/03/2022 Nature of Claim: TP Claim No: SNM22D201870/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX2713H**

Make & Model: TOYOTA NOAH HYBRID, 1.8 X CVT (A) Engine No: 2ZR0F56876

Reg. Date: 04/01/2021 (Man. Year: 2020) Chassis No: ZWR800444462

Colour: Metallic Silver Odometer: 79870 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: West Lake 9 mm Rear Left Side: Powertrac 5 mm

Front Right Side: West Lake 9 mm Rear Right Side: Powertrac 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,014.50	2,592.65	4,421.85	63.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	610.00	2,040.00	76.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,664.50	3,202.65	6,461.85	66.86
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	9,664.50	2,400.00	7,264.50	75.17
+ GST 7.00/7.00% (S\$)	676.52	168.00	508.52	75.17
Nett Amount (S\$)	10,341.02	2,568.00	7,773.02	75.17

INSPECTION

Date of Assignment: 22/03/2022

Date Inspected: 22/03/2022 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2022)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX2713H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDE DOOR O/S	Bent	1,809.00 FL	*1,809.00 FL
2	1		*SLIDE DOOR WINDOW CHANNEL O/S	Cut	176.00 FL	*176.00 FL
3	1		*SLIDE DOOR WEATHERSTRIP O/S	Cut	258.00 FL	*258.00 FL
4	1		*SLIDE DOOR OUTER HANDLE O/S	Serviceable	371.00 FL	*- FL
5	1		*SLIDE DOOR MOTOR O/S	Serviceable	966.00 FL	*- FL
6	1		*SLIDE DOOR LOCK O/S (2 Pcs)	Frt Dented/Jammed	792.00 FL	*358.20 FL
7	2		*SLIDE DOOR ROLLER LOWER O/S	Serviceable	338.00 FL	*- FL
8	1		*SLIDE DOOR ROLLER UPPER O/S (2 Pcs)	Distorted (1 Pc only)	256.00 FL	*128.00 FL
9	1		*REAR FENDER ROLLER RAIL O/S	Serviceable	199.00 FL	*- FL
10	1		*REAR FENDER O/S	Repair	1,267.00 FL	*- FL
11	1		*REAR FENDER GLASS MOULDING O/S	Not Necessary	289.00 FL	*- FL
12	2		*SLIDE DOOR PILLAR BLACK STICKER O/S	Necessary	96.00 FL	*96.00 FL
13	1		*SLIDE DOOR INNER TRIM BOARD O/S	Mtg Cracked	573.00 FL	*573.00 FL
14	1		*SLIDE DOOR WINDOW MOTOR O/S	Serviceable	335.00 FL	*- FL
15	1		*SLIDE DOOR WINDOW REGULATOR O/S	Serviceable	298.00 FL	*- FL
16	1		*SLIDE DOOR WINDOW INNER TRIM O/S	Serviceable	145.00 FL	*- FL
17	1		*SLIDE DOOR CLOSE SENSOR O/S	Serviceable	798.00 FL	*- FL
18	1		*SLIDE DOOR OUTER HANDLE SWITCH O/S	Serviceable	128.00 FL	*- FL
19	8		*SLIDE DOOR INNER TRIM BOARD CLIPS O/S	Necessary	44.00 FS	*44.00 FS
20	1		*REAR FENDER GLASS SEALANT O/S	Not Necessary	100.00 FS	*- FS
21	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	9,288.00 3,442.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,273.50 849.55
					Total Parts (\$\$)	7,014.50 2,592.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,200.00	250.00
2	TO DISCONNECT DOOR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS OF POWER WINDOWS	New	100.00	20.00
3	TO REMOVE AND REFIT O/S SLIDE DOOR COMPONENTS TO FACILITATE REPLACEMENT,CHECK ALIGNMENT	New	100.00	60.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,000.00	250.00
5	TO REMOVE AND REFIT O/S REAR FENDER GLASS TO FACILITATE REPAIR	New	150.00	0.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
Gross Labour Cost (\$\$)			2,650.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >