

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22002657/KQY3E2

Date: 30/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001961247		
Claimant Vehicle No :	YP2396P	Insured Vehicle No :	SLP3829E		
Date of Loss:	19/03/2022	Nature of Claim:	TP	Claim No:	271637

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP2396P		
Make & Model:	mitsubishi canter, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C08956
Reg. Date:	22/04/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20400
Colour:	White	Odometer:	105759 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8 (D)
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,600.00	2,600.00	2,000.00	43.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	600.00	660.00	52.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,860.00	3,200.00	2,660.00	45.39
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	5,860.00	2,550.00	3,310.00	56.48

INSPECTION

Date of Assignment:	23/03/2022	
Date Inspected:	01/04/2022 Inspected At:	TSR AUTOMOTIVE PTE LTD (HQ) 160 SIN MING DRIVE, #06-01 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 May 2022)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sdeb (cbu) (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP2396P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE CENTER DOOR PANEL ASSY	Bent	4,000.00 FS	*2,400.00 FS
2	1		*LH SIDE CENTER DOOR PANEL STICKER	Necessary	600.00 FS	*200.00 FS
3	1		*LH SIDE SLIDE DOOR RAILING (NPA)	Repair	0.00 FS	*- FS
Total Parts (S\$)						4,600.00 2,600.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	600.00	250.00
2	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	600.00	350.00
3	CHECKING WIRING SYSTEM	New	60.00	0.00
Gross Labour Cost (\$)			1,260.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >