



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 9976K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	985.90	-
2	REAR BUMPER BRACKET L/R @\$39.00	NOT NECESSARY	78.00	-
2	REAR BUMPER SIDE RETAINER L/R @\$59.00	NOT NECESSARY	118.00	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	46.80	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	260.30	-
1	REAR TAIL GATE	NOT NECESSARY	1,570.00	-
1	REAR TAIL GATE LOCK	SERVICEABLE	125.10	-
1	REAR TAIL LAMP LH	NOT NECESSARY	452.50	-
1	REAR TAIL GATE WEATHER-STRIP	SERVICEABLE	120.30	-
	LESS 20% DISCOUNT		-751.38	-
			3,005.52	-
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	38.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	34.00	-
1	SET REAR WINDSCREEN GLASS INNER SEAL MOULDING (SN)	NOT NECESSARY	92.10	-
1	REAR TAIL GATE 'STREAM' EMBLEM (SN)	NOT NECESSARY	38.80	-
2	REAR BUMPER REVERSE SENSOR @\$115.00 (SN)	NOT NECESSARY	230.00	-
			432.90	-
<u>LABOUR</u>				
	SPRAY PAINTING ON ABOVE NEW & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		800.00	200.00
	REMOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT DENTS ON REAR END PANEL, JACK OUT DAMAGED PANEL, PANEL BEATING, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE REPAIRS, RESHAPE, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVANT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		850.00	200.00
	TO TRANSFER REAR TAIL GATE MECHANISM & COMPONENTS.	NOT NECESSARY	80.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING, RECONNECTION SOCKET, LIGHTING SYSTEM, WIPER MOTOR, & CENTRE LOCKING SYSTEM FOR PROPER FUNCTION.	NOT NECESSARY	50.00	-
	TO REMOVE & REINSTALL REAR WINDSCREEN GLASS TO ASSIST REPAIR.	NOT NECESSARY	120.00	-
	TO APPLY UNDERCOATING, ANTI-RUST PROOFING ON AFFECTED PANELS & RE-SEAL WELDED PORTIONS.	NOT NECESSARY	100.00	-
	TO REINSTALL REAR BUMPER REVERSE SENSOR & CHECK FOR PROPER FUNCTION.	NOT NECESSARY	120.00	-
	TO SUPPLY REAR WINDSCREEN GLASS SEALANT.	NOT NECESSARY	50.00	-
			2,170.00	400.00
GRAND TOTAL			5,608.42	400.00
RECOMMENDED COST OF REPAIRS				400.00

Report Ref No. CS3/ASM21012007/Dqy3e2-1

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.