

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S1M03MX9 Date: 24th May 2022

Our Ref: CS3/ASM21012007/Dqy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJD 9976K INSURED VEHICLE: SHC 5731E ACCIDENT DATE: 20/11/2021

We thank you for your instruction on 21/03/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJD 9976K from M/s KTO Automobile Assessors.
- b) Singapore Accident Statement of Vehicles SJD 9976K and SHC 5731E.
- c) Final Repair Bill of SJD 9976K from M/s JL Auto Services Pte Ltd.
- d) Colour damaged vehicle photographs of SJD 9976K.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SJD 9976K

Make & Model : Honda Stream 1.8A

Chassis Number : RN61062325

Year of Registration : 2008 Engine Capacity : 1799 cc

- 2. We recommend that the repairs of the entire damage require about _____ 2 (Two) ____ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.