

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002663/AYA3Q2**Date:** 28/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070016631
Claimant Vehicle No :	SMU9840T	Insured Vehicle No :	SGU3228Y
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	6012769625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU9840T	Engine No:	1NZR784220
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707173124
Reg. Date:	10/09/2020 (Man. Year: 2019)	Odometer:	110042 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,080.59	5,719.71	4,360.88	43.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,050.00	1,510.00	42.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,640.59	7,769.71	5,870.88	43.04
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	13,640.59	6,200.00	7,440.59	54.55
+ GST 8.00/8.00% (S\$)	1,091.25	496.00	595.25	54.55
Nett Amount (S\$)	14,731.84	6,696.00	8,035.84	54.55
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,063.45		
Global Sum Settlement (S\$)		7,060.00		

INSPECTION

Date of Assignment:	22/03/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	22/03/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Distorted	1,350.80 FL	*1,086.00 FL
2	1		*TAIL GATE LOGO	Necessary	80.00 FL	*80.00 FL
3	1		*TAIL GATE HYBRID EMBLEM	Necessary	60.00 FL	*60.00 FL
4	2		*TAIL GATE HINGE	Not Necessary	178.00 FL	*- FL
5	2		*TAIL GATE DAMPER	Not Necessary	377.80 FL	*- FL
6	1		*TAIL GATE LOCK	Damaged	281.70 FL	*281.70 FL
7	1		*TAIL GATE WEATHERSTRIP	Cut	282.30 FL	*282.30 FL
8	1		*TAIL GATE LAMP	N/S Cut	760.00 FL	*380.00 FL
9	1		*TAIL GATE DETECTOR	Cracked	250.00 FL	*153.00 FL
10	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	197.10 FL	*197.10 FL
11	1		*TAIL GATE WIPER BLADE MOTOR	Not Necessary	360.50 FL	*- FL
12	1		*NUMBER PLATE GARNISH	Chipped	298.60 FL	*298.60 FL
13	1		*REAR BUMPER	Distorted	830.50 FL	*654.00 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	192.80 FL	*192.80 FL
15	1		*REAR BUMPER CENTRE	Deformed	350.00 FL	*350.00 FL
16	1		*REAR BUMPER SIDE	N/S Cut	466.40 FL	*233.20 FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	186.40 FL	*- FL
18	1		*REAR BUMPER TOWING COVER	Deformed	70.20 FL	*70.20 FL
19	1		*REAR FENDER INNER TRIM BOARD	N/S Cracked	1,758.40 FL	*688.00 FL
20	1		*TAILLAMP LH	Cracked	520.20 FL	*520.20 FL
21	1		*REAR END PANEL (OUTER)	Dented	689.75 FL	*689.75 FL
22	1		*REAR END PANEL (INNER)	Repair	544.60 FL	*- FL
23	1		*REAR END PANEL TOP GARNISH	Deformed	233.60 FL	*233.60 FL
24	1		*REAR FLOOR PANEL	Repair	1,225.30 FL	*- FL
25	1		*TOOLS TRAY	Cracked	322.50 FL	*322.50 FL
26	1		*TOOLS TRAY COVER	N/S Cut	560.00 FL	*280.00 FL
27	1		*REAR NUMBER PLATE	Dented	50.00 FS	*30.00 FS
28	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
29	1		*SET TAIL GATE INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
30	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
31	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
34	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
35	1		*REVERSE SENSOR	Necessary	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,187.45	7,482.95
- List Item Discount on L Items 25.00/25.00% (S\$)	3,106.86	1,763.24
Total Parts (S\$)	10,080.59	5,719.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	150.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	150.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
8	TRANFER TAILGATE MECHANISM	New	100.00	80.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			3,560.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >