

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22002665/UQY3E2

**Date:** 20/06/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001684669		
<b>Claimant Vehicle No :</b>	SMY3666Z	<b>Insured Vehicle No :</b>	GBF9723H		
Date of Loss:	22/01/2022	Nature of Claim:	TP	Claim No:	268740

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3666Z	Engine No:	CB00674
Make & Model:	PORSCHE CAYMAN, 3.4 GTS (981) PDK E6 (A)	Chassis No:	WP0ZZZ98ZBU770129
Reg. Date:	24/11/2010 (Man. Year: 2010)	Odometer:	66843 km
Colour:	Grey/White		
Engine Capacity:	3436 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	265/35 R19
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,107.60	3,861.40	13,246.20	77.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	1,430.00	2,300.00	61.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>20,837.60</b>	<b>5,291.40</b>	<b>15,546.20</b>	<b>74.61</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,200.00</b>		
<b>Nett Amount (\$\$)</b>	<b>20,837.60</b>	<b>4,200.00</b>	<b>16,637.60</b>	<b>79.84</b>

### INSPECTION

Date of Assignment:	23/03/2022	
Date Inspected:	17/05/2022	Inspected At: Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB Singapore 417800
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2022)
<b>Parts:</b>	M1-COUPE	PORSCHE CAYMAN 3.4 GTS (981) PDK E6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMY3666Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SPOILER	Not Necessary	1,023.00 FL	*- FL
2	2		*REAR TAILLAMPS	Not Necessary	3,225.20 FL	*- FL
3	1		*REAR END PANEL	Repair	1,313.40 FL	*- FL
4	1		*REAR BUMPER SPORT	Dented / Deformed	3,877.60 FL	*2,821.00 FL
5	2		*REAR BUMPER BRACKETS	Not Necessary	554.40 FL	*- FL
6	1		*SET REAR BUMPER CLIP	Necessary	187.00 FL	*80.00 FL
7	1		*REAR BUMPER INNER SPONGE	Not fitted	121.00 FL	*- FL
8	1		*REAR BUMPER LOWER EXHAUST HEAT SHIELD	Bent	545.60 FL	*485.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	946.00 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	954.80 FL	*- FL
11	1		*REAR BUMPER PDC SENSORS (4PCS)	Shorted(1Pc Only)	2,156.00 FL	*260.00 FL
12	1		*SET REAR NUMBER PLATE	Cracked	250.00 FS	*80.00 FS
13	1		*REAR BUMPER 3M STICKER	Necessary	1,200.00 FS	*500.00 FS
14	1		*SET REAR EXHAUST TAIL PIPE	Serviceable	2,244.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>18,598.00</b>	<b>4,226.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,490.40	364.60
<b>Total Parts (\$\$)</b>	<b>17,107.60</b>	<b>3,861.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	200.00	50.00
4	TO APPLY UNDERCOATING	New	200.00	0.00
5	PANEL BEATING	New	1,600.00	800.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>3,730.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >