

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22002667/AQY3Q2**Date:** 16/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004192100

**Claimant Vehicle No :** SMV775C **Insured Vehicle No :** SLD3959B

Date of Loss: 21/03/2022 Nature of Claim: TP Claim No: SNM22D201952/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMV775C**

Make & Model: TOYOTA PRIUS, 1.5 (A) Engine No: 2ZR2H39377

Reg. Date: 16/09/2020 (Man. Year: 2020) Chassis No: JTDZS3EU80J060567

Colour: White Odometer: 51572 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,580.85	2,723.00	3,857.85	58.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,003.18	4,293.18	4,710.00	52.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>15,584.03</b>	<b>7,016.18</b>	<b>8,567.85</b>	<b>54.98</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	1,090.88	491.13	599.75	54.98
<b>Nett Amount (\$\$)</b>	<b>16,674.91</b>	<b>7,507.31</b>	<b>9,167.60</b>	<b>54.98</b>

**INSPECTION**

Date of Assignment: 22/03/2022

Date Inspected: 25/04/2022 Inspected At: 17 UBI ROAD 4 SINGAPORE 408611

Estimated Period of Repair: 4.0 days Repairer: Borneo Motors (S) Pte Ltd (Pandan)

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2022)
<b>Parts:</b>	144	TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMV775C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*COVER,RR BUMPER	Distorted	589.50 FS	*589.50 FS
3	1		*SUPPORT ,RR BUMPER	Not Necessary	151.20 FS	*- FS
4	1		*RETAINER ,RR BUMPER	Necessary	62.70 FS	*62.70 FS
5	10		*CLIPS	Necessary	43.00 FS	*43.00 FS
6	1		*REINFORCEMENT	Not Necessary	230.20 FS	*- FS
7	1		*ARM SUB-ASSY ,RR	Not Necessary	186.30 FS	*- FS
8	1		*SPOILER ,RR NO.1	Deformed	899.70 FS	*899.70 FS
9	1		*PANEL SUB-ASSY ,BODY	Repair	738.00 FS	*- FS
10	1		*PANEL SUB-ASSY	Repair	1,023.30 FS	*- FS
11	1		*PLATE BACK DOOR	Not Necessary	192.50 FS	*- FS
12	1		*PANEL SUB-ASSY ,BACK	Repair	1,177.30 FS	*- FS
13	1		*EMBLEM ASSY	Necessary	67.20 FS	*67.20 FS
14	1		*PLATE ,BACK DOOR	Necessary	67.20 FS	*67.20 FS
15	1		*PLATE ,LUGGAGE COMPT	Not Necessary	58.00 FS	*- FS
16	1		*LENS & BODY RR	Cracked	730.90 FS	*730.90 FS
17	1		*BACK SENSOR 070 WHITE PEARL	Not Necessary	101.05 FS	*- FS
18	1		*DUCT ASSY ,QUARTER	Deformed	169.40 FS	*169.40 FS
19	1		*REFLECTOR ASSY	Missing	63.40 FS	*63.40 FS
<b>Total Parts (S\$)</b>					<b>6,580.85</b>	<b>2,723.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	New	183.18	183.18
2	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	180.00	180.00
3	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	180.00	180.00
4	SUPPLY SEALANT REAR END PANEL	New	60.00	0.00
5	REMOVE & INSTALL REAR COMPARTMENT CARPET GARNISH AND TRIMMING TO ASSIST REPAIR	New	360.00	360.00
6	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
7	REPLACE REAR EH ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR RH ACCIDENT AFFECTED AREAS	New	4,320.00	1,440.00
8	RESPRAY JOB ON REAR RH ACCIDENT AFFECTED AREAS	New	3,540.00	1,770.00
<b>Gross Labour Cost (\$)</b>			<b>9,003.18</b>	<b>4,293.18</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >