

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002671/ETCE2

Date: 09/05/2022

REFERENCE

Insured/Claimant:	MUHAMMAD HAFIZ BIN JAMAL	Policy No:	1700060705	
Date of Loss:	20/03/2022	Nature of Claim:	OD	Claim No: 6531738652SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7831E	Engine No:	4B12TP2745
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT 4WD (A)	Chassis No:	JMYXTGF3WJZ000347
Reg. Date:	04/10/2017 (Man. Year: 2017)	Odometer:	69978 km
Colour:	Blue		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	S\$80,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	854.67	834.67	20.00	2.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,440.00	950.00	490.00	34.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,294.67	1,784.67	510.00	22.23
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	1,694.67	1,184.67	510.00	30.09
+ GST 7.00/7.00% (S\$)	118.63	82.93	35.70	30.09
Nett Amount (S\$)	1,813.30	1,267.60	545.70	30.09

INSPECTION

Date of Assignment:	23/03/2022	
Date Inspected:	23/03/2022 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
2	1		*GARNISH, FR BUMPER SIDE	Broken	220.00 FL	*220.00 FL
3	1		*FACE, FR BUMPER	Broken	851.00 FL	*851.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					1,101.00	1,081.00
- List Item Discount on L Items 23.00/23.00% (\$)					246.33	246.33
Total Parts (\$)					854.67	834.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER PANEL & AFFECTED AREA	New	900.00	450.00
2	PAINT WORK ON FRT BUMPER PANEL	New	350.00	350.00
3	TO APPLY SEALANT ON AFFECTED AREA	New	40.00	0.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			1,440.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >