

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22002672/KYA3Q2**Date:** 20/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900006558
Claimant Vehicle No :	SGZ7409P	Insured Vehicle No :	SMH5829Y
Date of Loss:	21/03/2022	Nature of Claim:	TP
		Claim No:	4746607211SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGZ7409P	Engine No:	1NZX619664
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305026922
Reg. Date:	15/11/2007 (Man. Year: 2007)	Odometer:	258832 km
Colour:	Metallic Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50Z R16	Rear Tyre Size:	205/50Z R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,264.50	2,221.62	1,042.88	31.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,330.00	450.00	25.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,044.50	3,551.62	1,492.88	29.59
Approved Total (Overridden) (\$\$)		2,800.00		
Nett Amount (\$\$)	5,044.50	2,800.00	2,244.50	44.49
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,207.45		

INSPECTION

Date of Assignment:	30/03/2022	Tropical Tech Automobile Services (HQ) BLK 5032 ANG MO KIO AVENUE 3, #01-303 INDUSTRIAL PARK 2 Singapore 569535
Date Inspected:	30/03/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Buckled	862.00 FL	*681.20 FL
2	1		*REAR BOOT EMBLEM	Necessary	87.00 FL	*53.90 FL
3	1		*REAR BOOT VIOS DESIGNATION	Necessary	97.00 FL	*42.50 FL
4	2		*REAR BOOT HINGE	Repair	156.00 FL	*- FL
5	1		*REAR BOOT LOCK	Dented	156.00 FL	*109.50 FL
6	1		*REAR BOOT RUBBER (\$152.20) (50%)	Distorted / Dented	141.75 FS	*76.10 FS
7	2		*REAR TAIL LAMP	Cracked	656.00 FL	*656.00 FL
8	1		*REAR END PANEL	Bent	724.00 FL	*590.00 FL
9	1		*REAR END PANEL TOP GARNISH	Dented	218.00 FL	*158.60 FL
10	1		*REAR BUMPER	Buckled	517.00 FL	*517.00 FL
11	1		*REAR BUMPER SIDE BRACKET (SMALL)	N/S Dented / O/S Serviceable	104.00 FL	*52.00 FL
12	2		*REAR BUMPER SIDE BRACKET (BIG)	Serviceable	180.00 FL	*- FL
13	1		*REAR LICENSE PLATE	Serviceable	25.00 FS	*- FS
14	1		*SET REAR BUMPER PARKTRONIC SENSOR KIT	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,203.75	2,936.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	939.25	715.18
Total Parts (\$\$)	3,264.50	2,221.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND TRANSFER REAR BOOT NECEAASRY ATTACHMENT SPART PART ITEMS }	New	700.00	600.00
2	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
3	REMOVE AND REFIT REAR BOOT ,REAR BOOT EMBLEM ,REAR BOOT TOYOTA VIOS DESIGNATION,REAR BOOT LOCK ,REAR TAIL LAMP ,REAR END PANEL TOP GARNISH ,REAR BUMPER ,REAR BUMPER PARKTRONIC SENSOR KIT ,REAR BUMPER SIDE BRACKET (SMALL) ,REAR BUMPER SIDE BRACKET (BIG) }	New	0.00	0.00
4	HEAT/WELD /CUT/RENEW REAR END PANEL,HEAT /WELD /BEATING /PULL /STRAIGHTEN /ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	0.00	0.00
5	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	100.00	50.00
6	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
7	UNDER COATING ON REAR DAMAGED PORTION	New	200.00	60.00
8	PUTTY/ PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR END PANEL ,REAR BUMPER ,REAR BUMPER PARKTRONIC SENSOR KIT	New	700.00	600.00
Gross Labour Cost (S\$)			1,780.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >