

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG22002673/ETCN2**Date:** 17/04/2022**REFERENCE**

Insured/Claimant: MOHAMMED SHAFIK BIN MD SOM
Date of Loss: 22/03/2022

Policy No: 1700088815
Nature of Claim: OD Claim No: 8246175387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8304T**
Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGHH687628
Reg. Date: 15/12/2017 (Man. Year: 2017) Chassis No: KNAFX411MJ5755396
Colour: White Odometer: 70711 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 4 mm
Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,616.80	5,089.20	1,527.60	23.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	3,310.00	2,190.00	39.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,116.80	8,399.20	3,717.60	30.68
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	11,516.80	7,799.20	3,717.60	32.28
+ GST 7.00/7.00% (S\$)	806.18	545.94	260.24	32.28
Nett Amount (S\$)	12,322.98	8,345.14	3,977.84	32.28

INSPECTION

Date of Assignment: 23/03/2022

Date Inspected: 23/03/2022 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,LH	Broken	1,707.00 FL	*1,707.00 FL
2	1		*LAMP ASSY-HEAD,RH	Not Necessary	1,707.00 FL	*- FL
3	1		*PANEL ASSY-HOOD	Dented	1,384.00 FL	*1,384.00 FL
4	1		*PANEL-FENDER,LH	Dented	482.00 FL	*482.00 FL
5	1		*HINGE ASSY-HOOD,RH	Not Necessary	34.00 FL	*- FL
6	1		*HINGE ASSY-HOOD,LH	Not Necessary	34.00 FL	*- FL
7	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
8	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
9	1		*MOULDING-FRT BPR LICENSE PLATE	Broken	18.00 FL	*18.00 FL
10	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
11	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
12	1		*GARNISH-RADIATOR GRILLE,UPR	Broken	54.00 FL	*54.00 FL
13	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	29.00 FL	*- FL
14	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	91.00 FL	*91.00 FL
15	1		*BRACKET-FR BUMPER SIDE MTG,LH	Broken	13.00 FL	*13.00 FL
16	1		*BRACKET-FR BUMPER SIDE MTG,RH	Not Necessary	13.00 FL	*- FL
17	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
18	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
19	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
20	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 FL	*84.00 FL
21	1		*RAIL ASSY-FR BUMPER	Dented	496.00 FL	*496.00 FL
22	1		Supplementary			
			*LAMP ASSY-FRONT FOG, LH	Broken	241.00 FL	*241.00 FL
23	1		Supplementary			
			*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL
24	1		Supplementary			
			*CLIP (10PCS)	Necessary	10.00 FL	*10.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,246.00	6,344.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,629.20	1,254.80
Total Parts (\$\$)	6,616.80	5,089.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BONNET,SUPPORT,FRT LH FENDER & AFFECTED AREA.REPAIR ON FRT RH FENDER	New	2,800.00	1,000.00
2	PAINT WORK ON FRT BUMPER,BONNET,FRT LH DOOR & LH FRT FENDER	New	1,750.00	1,400.00
3	REMOVE & INSTALL RADIATOR,CONDENSER FOR FACILITATE REPAIR	New	120.00	120.00
4	TO TOP UP AIRCON GAS	New	80.00	80.00
5	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
6	PERFORM RUST PREVENTION	New	40.00	40.00
7	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
9	APPLICATION TO BREAK REAR OPC PLATE AND RESEAL	New	80.00	80.00
10	REPLACE FRONT SUPPORT PANEL	New	400.00	400.00
Supplementary				
Gross Labour Cost (\$\$)			5,500.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >